

Fahn, Patrick J.

From: Luke B. Toso <ltoso@wenck.com>
Sent: Tuesday, November 20, 2012 8:45 AM
To: Fahn, Patrick J.; Gallion, Joshua C.; Marohl, Christopher A.
Subject: Construction Inspection Notes
Attachments: PU-09-674 Ottertail 0.53 T-Line Reroute.pdf; PU-08-107 Ottertail 13mi T-Line.pdf; PU-08-73 Ash 9.5mi T-Line.pdf

Good Morning,

Attached, please find a copy of construction inspection notes for three projects:

- PU-08-107 – Ottertail 13 mile T-Line, Barnes/Steel Co.
- PU-09-674 – Ottertail 0.53 mile T Line, Sargent Co.
- PU-08-73 – Ashtabula Wind 9.5 mile T Line, Barnes Co.

The inspection was completed yesterday, 11/18/2012 and no noncompliance issues were noted; the project was constructed according to the PSC Order. A full inspection report will be submitted for these projects. Please let me know if you have any questions.

Best,

Luke

Luke B. Toso, Botanist/Natural Resources Specialist
Wenck Associates Inc., 301-1st Street NE, #202, Mandan, ND 58554-3370
www.wenck.com | ltoso@wenck.com | D 701.751.6129 | F 701.751.3372 | C 651.925.7267 |



POLARIS GROUP

.53 mile diversion

Name: L. Tasso Date: 11/11/12
Project: 2579-09 No. _____
Desc. _____
Checked By: _____ Sheet _____ of _____

GDS

291

Diverts around water body. Poles were outside of wetland, with no apparent erosion or sedimentation.

Bird diverters are in place where specified.

old poles will be removed when they float to surface landowner has requested them.

Several photos taken. No trees removed. No problems or non compliance issues noted.

Todd Langston, Reconstruction Manager
218 770 6376