

-Info-Public Service Commission

From: Emmy Baskerville <ebaskerville@houstoneng.com>
Sent: Wednesday, October 29, 2014 10:16 AM
To: -Info-Public Service Commission
Cc: Lein, Jerry R.; Bart Schultz
Subject: Bison 4 Wind Project Permit Inspection Compliance Field Notes (PU-13-127)
Attachments: PU-13-127 field-notes-10-22-14.pdf

Please find the attached field notes for the permit compliance inspection on the **Bison 4 Wind Project (PU-13-127)**. The second compliance inspection site visit took place last Wednesday, October 22nd, 2014. No non-compliant items were identified during our site visit. Construction has been completed on portions of the Bison 4 site and portions are actively under construction. Silt fencing, dust control, erosion control measures and seeding were identified throughout the sites. Restoration activities were also observed in and around finished sites. I will follow up with a complete progress report in the next few weeks.

Thank you,

Emmy Baskerville

Environmental Scientist
Houston Engineering, Inc.

☎ 763.493.4522 | 📠 763.493.6669 | 📠 763.493.5572



6901 E Fish Lake Rd. , Suite 140 • Maple Grove, MN • 55369

www.houstoneng.com

This entire message (including all forwards and replies) and any attachments are for the sole use of the intended recipient(s) and may contain proprietary, confidential, trade secret, work-product, attorney-client or privileged information. Any unauthorized review, use, disclosure or distribution is prohibited and may be a violation of law. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message.

Bison 4- 10/22/14

⊕ 11:35 → entering area, dust management on gravel roads observed.

⊕ 11:40 → meet Daniel McCartney, ^{begin visit.} visiting completed turbines, restoration to be completed

421: biorolls, erosion control in place

422: ok

423: ok

424: biorolls observed in ROW ditch

ROAD b/w 424 & 425 avoids historical site

401: major archaeo/historic site, const. avoids entire site - ok

402: silt fencing observed access road avoids historic/archaeo site

403: ok

404: ok, seeding, restoration complete

405: biorolls observed in ROW ditch

431: archaeo/historic site avoided

string 426-431

- seeding in adjacent ROW complete
- restoration complete

457: under construction

456: under const.

Bison 4 - 10/22/14 cont.

463: visited previously, access
road avoids archaeo/historic
site.
- silt fence observed.

462-461: ok

MET weather tower: ok, const.
complete

460: grading taking place, okay

433: under const - pic

434: ~~at~~ major archaeological site.
Avoided

452: under const. crane on site

445: under const. okay

439: ~~by~~ recent hydro SEED-PIC
silt fence observed

Wetland avoided b/w 424 & 423

444: archaeological/hist. site
Avoided - pic

417 & 418: okay

⊗ END SITE VISIT @ approx 2pm