



871 Jefferson Ave.  
Suite 102  
St Paul, MN 55102

September 28, 2015

Victor Shock  
Public Utility Analyst  
North Dakota Public Service Commission  
600 E. Boulevard Ave., Dept 408  
Bismarck, ND 58505-0480



Mr. Shock,

E3 Environmental, LLC (E3) conducted an on-site inspection of the Hess Hawkeye Pipeline Project (PU-15-31) and the Basin Electric Lonesome Creek Station Phase III Project (PU-14-852) in September 2015. Enclosed please find hard copies of each of these reports.

Please contact me at 651-282-0652 or Tyler Danielson 651-282-0651 if you have any questions or concerns.

Regards,

A handwritten signature in cursive that reads 'Katie Schmidt'.

Katie Schmidt  
E3 Environmental, LLC



## LONESOME CREEK STATION PHASE III PROJECT

GENERAL INFORMATION		
<b>Environmental Inspector:</b>  Bernie Campbell	<b>Inspection Date &amp; Time:</b>  09/15/2015	<b>Report Number:</b>  LCSP3-20150916-BC
<b>Weather:</b>  55* clear & calm	<b>Precipitation (last event):</b>  9/5/15  7/8"	<b>On-Site Staff Worked With &amp; Affiliation:</b>  Chris Miller – Basin Electric
	<b>ROW Conditions:</b>  Dry	
DAILY CONSTRUCTION ACTIVITIES		
<p>Provide a description of construction activities (i.e. construction techniques, meetings, construction progress, route adjustments, etc.). Additionally, provide a description of general environmental impact mitigation efforts on site (i.e. top soil segregation, depth of cover, fuel storage areas, erosion control devices, restoration activities etc.)</p> <p>Site grading, other earth works, structure construction, and general construction are all on-going. No adjustments in construction plans were relayed to inspector.</p> <p>Top soil storage had been prepared for seeding, which will take place in the next few days per Chris Miller.</p> <p>ECDs west of pond; silt fence installed incorrectly (south portion not keyed in), silt fence overwhelmed and knocked down (north portion).</p> <p>Generally the site demonstrates good housekeeping and refuse management.</p>		
SIGNATURE		
<b>Signature:</b> Bernie Campbell	<b>Date:</b> 09/15/15	



## LONESOME CREEK STATION PHASE III PROJECT

OBSERVATION LOG		
Photo Number	Station Value	Comments
001	West of pond at outlet	Silt fence installed incorrectly, not keyed in
002	West of pond at outlet	Silt fence overwhelmed, knocked down
003	South of site	Top soil waiting to be seeded
004		
005		
006		
007		
008		
009		
010		
011		
012		




1. West of pond, silt fence installed incorrectly (not keyed in)




2. West of pond, silt fence overwhelmed and knocked down.




3. Top soil storage area in background, prepared for seeding.



4.



5.



6.