



low flow (60")  
culvert outlet

erosion  
feature

Image from the June 30, 2015 Coyote Creek Mine inspection picturing the erosion feature in relation to the low flow culvert outlet.

ND Public Service Commission August 27, 2015