



Image from the June 30, 2015 Coyote Creek Mine inspection picturing the erosion feature in relation to the low flow culvert outlet.

ND Public Service Commission August 27, 2015