

Casey Furey  
100 West Broadway, Suite 250  
P.O. Box 2798  
Bismarck, ND 58502-2798  
701.223.6585  
cfurey@crowleyfleck.com

June 22, 2017

Via hand delivery

Mr. Darrell Nitschke  
Executive Director  
North Dakota Public Service Commission  
600 E. Boulevard, Dept. 408  
Bismarck, ND 58505-0480  
ndpsc@nd.gov

Dear Mr. Nitschke:


In re: Cenex Pipeline, LLC  
10-Inch Refined Fuels Pipeline in Williams,  
Mountrail and Ward Counties, North Dakota  
Case No. PU-17-097  
Our File No. 020836-000001

Enclosed for filing please find 11 copies of Cenex's Spill History. This is exhibit No. 6 of the Commission's motion in this case dated May 10, 2017. An electronic version of the exhibit will be emailed to the Commission at the address above.

Please call should you have any questions.

Very truly yours,

Casey Furey



bw  
enc.

cc: John Hamre (via email)  
Patrick Fahn (w/o enclosures)  
Zachary Pelham (w/o enclosures)

Cenex Pipeline Spill History

1990 to Present

PU-17-97

Date	Pipeline	Location	Location Description	Product	Vol. Spilled (gal)	Cause	Cause Category	Reported To:	Comments
7/12/1993	Cenex	NW/4 Sec. 17, T1N, R27E	Lockwood--Johnson Lane	diesel & gasoline		dellamination-type failure in pipe wall (probably manufacturing defect)		MDEQ	
10/4/1995	Cenex	Section 14 T152N, R93W	4 miles west of Newtown, ND	UL gasoline	47712	line hit by contractor for state of North Dakota	outside force damage-- 3rd party	DOT	Soil removal was conducted.
12/11/1995	Cenex		Laurel	UL gasoline	630	line hit by contractor installing fiber optic communication cable on refinery property	outside force damage-- 3rd party	DOT	Soil removal was conducted.
9/20/2002	Cenex	N47.087, W104.767 N46deg 42.602min,	Glendive 7 Mi. Cr.	UL gasoline	41874	damage from drilling for replacement of pipe	outside force damage-- 3rd party	DOT	Soil removal was conducted.
9/1/2006	Cenex	W105deg 26.985min	MP 191	diesel	42		Equipment	DOT	
Mar. 2007	Cenex	N45.8352453,	Billings Post Office	diesel					This was a historic leak that was found when digging up an LI anomaly, which was an old welded patch. Soil removal was conducted.
8/28/2007	Cenex	W108.372207	MP 24	diesel	2	burn through during in-service welding on a mechanical sleeve		MDEQ	
9/7/2010	Cenex	N46.71782754 deg., W105.44123948 deg.	MP 191 receiver	diesel	151	failed internal seal on pressure indicator	Equipment Failure	DOT	Soil removal was conducted.
2/24/2012	Cenex	46.24913, -106.81986	MP 111 BV Upstream Flange	Diesel	7686	Flange Gasket Leak	Equipment Failure	DOT/NRC	Soil removal was conducted.
7/9/2013	Cenex		MP 81	gasoline	36,540	Third party excavator damaged pipeline	Outside force damage-- 3rd party	DOT/NRC	Soil removal was conducted.
12/9/2013	Cenex		Whoopup Creek Road west of Glendive	gasoline/diesel					This was a historic leak that was found when digging up an LI anomaly, which was an old welded patch. There was evidence of a previous soil removal.
3/28/2017	Cenex		BV 251.6 Minot to Fargo	gasoline/diesel		Failed underground valve fitting	Equipment Failure	MDEQ	Soil removal was conducted.
5/7/2017	Cenex		BV 185 Minot to Fargo	gasoline/diesel		Failed underground valve fitting	Equipment Failure	DOT/NRC	Soil removal was conducted.