

**MDU ND** (Total Leaks Repaired by Material Type excluding Leaks caused by Excavation & Above Ground Leaks)

Leak Material	2015	2016	2017
<b>Steel</b>	32	54	45
<b>Plastic</b>	28	45	27

