



## INCIDENT INVESTIGATION #209476

---



806 Bruegger St, Alexander, ND

### LOCATION DETAILS

**Event Date:** 06/24/2021 08:30 AM America/Denver

**Right-of-Way:**

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 3/4" Plastic

**Facility part of joint trench:** No

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Dirt 18" - 36"

**Arrival Date and Time:** 06/24/2021 10:10 AM America/Denver



**Distance from Ped to Ped:** 8ft

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** Yes

**Who Performed Repairs:** Utility Company

**Contractor Representative:** Briar Vogel

**Contractor Representative Phone Number:** (701) 690-0468

**Personnel On Site:** 1. MDU 2. BEK 3. ELM

**Vehicles/Equipment Being Used For Repairs:**

**Guards or Barricades On Site:** None

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:**

## **DAMAGER**

**Company Name:** BEK

**Contact:** Briar Vogel

**Contact Phone:** (701) 690-0468

**Type of Work:** DRAINAGE

**Damage Responder:** Sabrina, Sebastian

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Laura

**Utility Contact Phone:** (206) 755-4310

**Utility Representative:** Laura

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** No

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Bulldozer

**Work Performed:** Drainage

**Excavator downtime?** No

**Downtime hours:** No

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Contract Locator

**Work area white-lined:** No

**Ticket Number:** 21053859

**Date Located:** 06/02/2021 01:03 PM America/Denver

**Located By:** Benitez, Raul

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** No

**Interruption hours:**

**Customers Affected (approx.):** 1

## ROOT CAUSE

**Root Cause:** Excavator failed to maintain clearance after verifying marks

## COMMENTS

**Assessment Comments:** Utility exposed. Contractor still hit. Locator marks were accurate.

# NEW INCIDENT PHOTOS



Date: 06/25/2021 12:15 PM  
America/Denver

Latitude: 47.840829

Longitude: -103.643962

Heading: 183 degrees



Date: 06/25/2021 12:15 PM  
America/Denver

Latitude: 47.840829

Longitude: -103.643961

Heading: 197 degrees



Date: 06/25/2021 12:16 PM America/Denver

Latitude: 47.840829

Longitude: -103.643960

Heading: 244 degrees



Date: 06/25/2021 12:16 PM  
America/Denver

Latitude: 47.840830

Longitude: -103.643960

Heading: 179 degrees



Date: 06/25/2021 12:16 PM America/Denver

Latitude: 47.840829

Longitude: -103.643962

Heading: 243 degrees