



## INCIDENT INVESTIGATION #211506

---



506 Bruegger, Alexander, ND

### LOCATION DETAILS

**Event Date:** 08/27/2021 01:20 PM America/Denver

**Right-of-Way:**

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 3/4" Plastic

**Facility part of joint trench:** No

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Dirt < 18"

**Arrival Date and Time:** 08/27/2021 01:20 PM America/Denver

3 PU-21-377 Filed 09/03/2021 Pages: 6  
Incident Investigation  
ELM



**Distance from Ped to Ped:** 0ft

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** Yes

**Who Performed Repairs:** Utility Company

**Contractor Representative:** MDU- Bill Dutton

**Contractor Representative Phone Number:** (701) 770-3171

**Personnel On Site:** MDU, ELM, BEK

**Vehicles/Equipment Being Used For Repairs:** Shovel

**Guards or Barricades On Site:** None

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:** 2:00 PM America/Denver

## **DAMAGER**

**Company Name:** BEK Consultants

**Contact:** Briar Vogel

**Contact Phone:** (701) 690-0468

**Type of Work:** Drainage

**Damage Responder:** Sabrina, Sebastian

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Bill

**Utility Contact Phone:** (701) 770-3171

**Utility Representative:** Bill

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** Yes

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Unknown/Other

**Work Performed:** Drainage

**Excavator downtime?** No

**Downtime hours:** No

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Contract Locator

**Work area white-lined:** No

**Ticket Number:** 21103481

**Date Located:** 08/07/2021 09:06 AM America/Denver

**Located By:** Russell Scott

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** Yes

**Interruption hours:** 1

**Customers Affected (approx.):** 1

## ROOT CAUSE

**Root Cause:** Root Cause not listed above (comment required)

## COMMENTS

**Assessment Comments:** BEK raised gas service line to 506, due to clearance for concrete drainage line. BEK failed to notify anyone they had done this. Making line approximately 4-6" deep. BEK was doing final grade and snagged it with skid steer. MDU Dana/Chuck on-site. BEK rep acknowledged that they were at-fault.

# NEW INCIDENT PHOTOS



Date: 08/27/2021 02:52 PM  
America/Denver

Latitude: 47.843711

Longitude: -103.643899

Heading: 109 degrees




Date: 08/27/2021 02:52 PM America/Denver

Latitude: 47.843718

Longitude: -103.643936

Heading: 261 degrees




Date: 09/01/2021 12:01 PM America/Denver

Latitude: 47.843686

Longitude: -103.643902

Heading: 182 degrees



Date: 09/01/2021 12:01 PM  
America/Denver

Latitude: 47.843687

Longitude: -103.643900

Heading: 178 degrees