

GENERAL OBSERVATION REPORT

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833

Client

State of North Dakota
Attn: Brett Job
Abandoned Mine Lands Division
600 East Boulevard Ave Dept 408
Bismarck, ND 58505-0480

Project

2025 Lehigh Road Phase X &
Scranton Phase IV Material Testing
Bid #408.25.03.002
Stark & Bowman Counties, ND
Project Number: M4251009

General Information

Brett w/PCS requested Terracon to be on site for installed structural crack monitors at the above referenced project. Observed work was being performed by PCS.

The construction documents referenced for this inspection include: 2025 Lehigh Road phase X and Scranton Phase IV Material Testing AML project.

Summary of Services

Terracon representatives conducted structural surveys on 3 structures in Scranton.

Summary of Testing

Crack monitors were installed on the 3 structures. Exterior observations were completed with limited access to exposed foundation walls. Interior observations were not possible as the buildings were not accessible.

Compliance Statement

Based on our observations, construction activities at the above referenced locations appeared to be completed in general accordance with the project plans and specifications.

Services:

Terracon Rep.: Jade Jacob

Reported To:

Contractor: PCS

Report Distribution:

(1) State of North Dakota, Brett Job

43 AM-24-369 Filed 06/18/2025 Pages: 17
Pre-Construction Structural Survey
Terracon Consultants, Inc.

Reviewed By:

Patrick Coyne
Department Manager I

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P1) SE white garage

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P2) West side white garage

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P3) North side white garage

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P4) South side garage attached to house

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P5) West side garage

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P6) West side of house

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P7) North side of house

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P8) East side of house

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P9) Front of garage

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P10) South side of shed

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P11) East side of shed

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P12) West side fo shed

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P13) North side of shed

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P14) South side of garage crack monitor

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P15) East side of shed crack monitor

Photo Log

Report Number: M4251009.0001
Service Date: 06/12/25
Report Date: 06/18/25
Task: Materials Testing



1502 Grumman Ln, Ste 4
Bismarck, ND 58504-6070
701-258-2833



(P16) East side of white garage