



Public Service Commission

State of North Dakota

COMMISSIONERS

Brian P. Kalk
Randy Christmann
Julie Fedorchak

Executive Secretary
Darrell Nitschke

February 12, 2014

600 East Boulevard, Dept. 408
Bismarck, North Dakota 58505-0480
Web: www.psc.nd.gov
E-mail: ndpsc@nd.gov
Phone: 701-328-2400
ND Toll Free: 1-877-245-6685
Fax: 701-328-2410
TDD: 800-366-6888 or 711

Mr. John Didonato, Director
FPL Energy
700 Universe Boulevard
Juno Beach, FL 33408

RE: Post Construction Inspections, Case Nos. PU-05-205 and PU-06-312 Burleigh Wind Collector Substation and Oliver Wind Transmission Line

Dear Mr. Didonato:

The North Dakota Public Service Commission retained a third-party vendor to conduct post construction inspections under the authority provided in the above referenced cases. Below we provide a weblink to the third-party post construction inspection reports for your review and a link to the Commission's orders in these proceedings. We also list actions recommended in the post construction inspection report for follow-up by the Company to confirm compliance with the Commission orders.

Case No. PU-05-205

As per the post construction inspection report, the following information should be provided:

- FPL should provide a substation as built drawing or drawings, design specifications and fence dimensions for Commission's file. (Order Points 9 and 18)
- FPL should provide a letter to the Commission that the substation was constructed and operates in accordance with the National Electric Safety Code Standards. (Order Point 9)

The construction report can be found at:

<http://www.psc.nd.gov/database/documents/05-0205/183-010.pdf>

The Commission Order can be found at:

<http://www.psc.nd.gov/database/documents/05-0205/058-001.pdf>

Case No. PU-06-312

As per the post construction inspection report, the following information should be provided:

- FPL is required to submit a 10 year plan to the Commission annually under current laws and beginning every other year in 2014. To date, FPL has not complied with this provision (Order Point 5 and NDCC 49-22-04).

Page 2
Mr. John Didonato
February 12, 2014

- FPL should provide a letter to the Commission that the transmission line and collector substation were constructed and operate in accordance with the National Electric Safety Code Standards. (Order Point 7)
- FPL should provide as built drawing or drawings for the transmission line and substation for the Commission's file. (Order Point 18)
- According to the new Tree Mitigation Plan, Oliver County Wind, LLC (Oliver Wind) is a subsidiary of Nextera Resources, Inc. If Nextera Resources, Inc. now owns the transmission line and the Oliver Substation, a modification to the Route Permit and Certificate of Corridor is required. (Order Point 19)

The construction report can be found at:

<http://www.psc.nd.gov/database/documents/06-0312/091-010.pdf>


The Commission Order can be found at:

<http://www.psc.nd.gov/database/documents/06-0312/020-020.pdf>

Please forward your response to the recommended Company actions, confirming these activities are complete, and describe actions and timelines for activities that are not complete. Please provide this documentation within 30 days.

If you have any questions regarding this letter, please contact me at 701-328-1035.

Sincerely,



Jerry Lein
Public Utility Analyst