

LANGDON WIND, LLC

March 13, 2014

Mr. Jerry Lein
Public Utility Analyst
North Dakota Public Service Commission
600 East Boulevard, Dept 408
Bismarck, ND 58505-0408

UPS Overnight Mail

RE: Langdon Wind, LLC
Post Construction Inspection, Case No. PU-07-026 and PU-07-722

Dear Mr. Lein:

Below please find Langdon Wind, LLC's ("the Company") response to your letter of February 11, 2014. The following list provides responses to your inquiries and references to requested documentation. These documents can be found on the enclosed CD. For activities that are not complete, we are still awaiting confirmation, conducting further research, and/or gathering the appropriate paperwork. An update on the status of these items will be provided to the Commission within 30 days.

PU-07-026

- Design and implementation of new erosion control measures for drainage crossings, junction boxes and Geotech fabric underlayment on access roads. (Order Point 14)
 - Langdon Wind hires contractors to repair any places where erosion may have occurred, along with any road repairs or upgrades. The site manager confirms that Geotech fabric is present under turbine string roads.
- Last tree and shrub survival report due in fall of 2014. (Order Point 16)
 - The Company plans to complete and submit this report by November 30, 2014.
- Maintenance of signs, in particular, no trespassing signs were missing, sometimes turned in the wrong direction or lying on the ground. (Order Point 23)
 - Site has ordered 25 additional "No Trespassing" signs to post around the property. Signs that were found to be in disarray have been repaired and pointed in the appropriate direction.
- Compliance with National Electric Safety Code. (Order Point 8)
 - Assessment underway. The Company will discuss its response with Staff.
- Construction according to Application and safety requirements. (Order Points 7, 8 and 23)
 - To the best of the Company's knowledge, construction was performed following all Application and safety requirements. If Staff seeks specific

Langdon Wind, LLC

130 PU-07-722 Filed 03/14/2014 Pages: 3
Response to Feb. 11, 2014 letter regarding third-party post construction inspection report

181 PU-07-26 Filed 03/14/2014 Pages: 3
Response to Feb. 11, 2014 letter regarding third-party post construction inspection report

information related to a particular requirement, the Company will work with Staff to provide the requested information.

- Post-construction reports of presence of threatened, endangered species or bald or golden eagles, if applicable. (Order Point 9)
 - During operation, the Company follows the site Wildlife Response and Reporting System Manual, which mandates that any and all avian injuries or fatalities observed within the site boundaries be reported. To date there have been no such incidents involving threatened, endangered species or bald or golden eagles. Any further requirements will be discussed with Staff.
- Reports of cultural, archeological, historical resources found, if applicable. (Order Point 10)
 - Please see relevant files “Langdon Cultural Resources Report” and “Langdon Cultural Report Mitigation Plan” on the enclosed CD.
- Notice of extraordinary events, if applicable: tower collapse, injury, death of threatened or endangered species or large number of birds or bats. (Order Point 24)
 - None of the extraordinary events cited in the Commission’s order have occurred at the site. The only reportable event that has occurred at the Langdon site occurred on 7/6/12 when there was a padmount oil spill in which greater than 25 gallons of transformer oil spilled. Please see file “Langdon Oil Spill Incident Report” on included CD for full report. This incident was reported to the North Dakota Department of Environment and Health in accordance with state law.
- Procedures for handling complaints. (Order Point 25)
 - Please see file “Langdon Complaint Procedures” on the enclosed CD.
- Mitigation of television & radio interference. (Order Point 29)
 - Research ongoing


PU-07-722

- Design and implementation of new erosion control measures for drainage crossings, junction boxes and Geotech fabric underlayment on access roads. (Order Point 14)
 - Langdon Wind hires contractors to repair any places where erosion may have occurred, along with any road repairs or upgrades. The site manager confirms that Geotech fabric is present under turbine string roads.
- Fulfillment of planned tree and shrub survival monitoring through 2014. (Order Point 16)
 - The Company plans to complete and submit this report by November 30, 2014.
- Maintenance of signs, in particular, no trespassing signs were missing, sometimes turned in the wrong direction or lying on the ground. (Order Point 23)
 - The Company has ordered 25 additional “No Trespassing” signs to post around the property. Signs that were found to be in disarray have been repaired and pointed in the appropriate direction
- Compliance with National Electric Safety Code. (Order Point 8)
 - Assessment Underway, the Company will discuss its response with Staff.

- Construction according to Application and safety requirements. (Order Points 7, 8 and 23)
 - To the best of the Company's knowledge, construction was performed following all Application and safety requirements. If Staff seeks specific information related to a particular requirement, the Company will work with Staff to provide the requested information.
- Post-construction reports of presence of threatened, endangered species or bald or golden eagles, if applicable. (Order Point 9)
 - During operation, the Company follows the site Wildlife Response and Reporting System Manual, which mandates that any and all avian injuries or fatalities observed within the site boundaries be reported. To date there have been no such incidents involving threatened, endangered species or bald or golden eagles. Any further requirements will be discussed with Staff.
- Reports of cultural, archeological, historical resources found, if applicable. (Order Point 10)
 - Please see relevant files "Langdon Cultural Resources Report" and "Langdon Cultural Report Mitigation Plan" on the enclosed CD.
- Notice of extraordinary events, if applicable: tower collapse, injury, death of threatened or endangered species or large number of birds or bats. (Order Point 24)
 - None of the extraordinary events cited in the Commission's order have occurred at the site. The only reportable event that has occurred at the Langdon site occurred on 7/6/12 when there was a padmount oil spill in which greater than 25 gallons of transformer oil spilled. Please see file "Langdon Oil Spill Incident Report" on included CD for full report. This incident was reported to the North Dakota Department of Environment and Health in accordance with state law.
- Procedures for handling complaints. (Order Point 25)
 - Please see file "Langdon Complaint Procedures" on the enclosed CD.
- Mitigation of television & radio interference. (Order Point 29)
 - Research ongoing

Thank you for your attention to this matter. Please feel free to contact me at (561) 304-5699 should you have any questions.

Sincerely,



Rebecca Kujawa
Vice President
Business Management – Midwest Region

Enclosures