

## Fahn, Patrick J.

---

**From:** Luke B. Toso <ltoso@wenck.com>  
**Sent:** Tuesday, November 20, 2012 8:45 AM  
**To:** Fahn, Patrick J.; Gallion, Joshua C.; Marohl, Christopher A.  
**Subject:** Construction Inspection Notes  
**Attachments:** PU-09-674 Ottetail 0.53 T-Line Reroute.pdf; PU-08-107 Ottetail 13mi T-Line.pdf;  
PU-08-73 Ash 9.5mi T-Line.pdf

Good Morning,

Attached, please find a copy of construction inspection notes for three projects:

- PU-08-107 – Ottetail 13 mile T-Line, Barnes/Steel Co.
- PU-09-674 – Ottetail 0.53 mile T Line, Sargent Co.
- PU-08-73 – Ashtabula Wind 9.5 mile T Line, Barnes Co.

The inspection was completed yesterday, 11/18/2012 and no noncompliance issues were noted; the project was constructed according to the PSC Order. A full inspection report will be submitted for these projects. Please let me know if you have any questions.

Best,

### Luke

Luke B. Toso, Botanist/Natural Resources Specialist  
Wenck Associates Inc., 301-1<sup>st</sup> Street NE, #202, Mandan, ND 58554-3370  
[www.wenck.com](http://www.wenck.com) | [ltoso@wenck.com](mailto:ltoso@wenck.com) | D 701.751.6129 | F 701.751.3372 | C 651.925.7267 |



Station 26 intersection Co Rd. 27. }  
gravel N of intersection }

Start: same substation as station 2579-07

300 - sub

301 - Bird diverters on this stretch

302 - spanned wetland

303 - GOP

304 - Running NS Now, GOP

305 - spanned wetland

306 - " " @ intersection of 27 + 26  
Diverters are still evident

307 - Another spanned wetland. Rather large H<sub>2</sub>O body

308 - Line x s road .25 mi S, from E to W side

309 - Another spanned wetland

310 - End of the line