

June 6, 2017

VIA HAND DELIVERY

Mr. Darrell Nitschke
Executive Secretary
North Dakota Public Service Commission
600 E. Boulevard, Dept. 408
Bismarck, ND 58505-0480

**RE: BAKKEN OIL EXPRESS, LLC
CASE NUMBER PU-13-825**

Dear Mr. Nitschke:

On January 24, 2017, North Dakota Public Service Commission ("Commission") staff sent Bakken Oil Express, LLC ("BOE") a letter addressing various issues noted in the post-construction inspection report ("Report") performed by the Commission's third-party inspector. Photo 12 in the Report depicted a pipeline marker had fallen along the route. Commission staff requested BOE submit evidence that the pipeline marker has been replaced.

To that end, please find enclosed for filing an original and ten (10) copies of a photograph depicting replacement of the pipeline marker at approximately Station 820+00 along the route. Also enclosed is a CD containing the referenced document in PDF format.

If you should have any questions, please advise.

Sincerely,



LAWRENCE BENDER

LB/dmk
Enclosure

cc: Sara Cardwell (via e-mail)

61534220_1.docx
Attorneys & Advisors
main 701.221.8700
fax 701.221.8750
fredlaw.com

Fredrikson & Byron, P.A.
1133 College Drive, Suite 1000
Bismarck, North Dakota
58501-1215

115 PU-13-825 Filed 06/06/2017 Pages: 2
Photo depicting replacement of pipeline marker
Bakken Oil Express, LLC
Lawrence Bender, Fredrikson & Byron, P.A