



four 10' by 10'
box culverts
under
construction

low flow (60")
culvert outlet

erosion
feature

Image from the June 30, 2015 Coyote Creek Mine inspection picturing the erosion feature in relation to the low flow culvert outlet.

ND Public Service Commission August 27, 2015