



811 Main St.
Suite 3400
Houston, TX 77002

P: (832) 519.2200
F: (832) 519.2250
www.Crestwoodlp.com

August 29, 2022

Mr. Patrick Fahn
Director, Public Utilities Division
North Dakota Public Service Commission
600 E Boulevard, Dept. 408
Bismarck, ND 58505-0480

RE: Response to January 22, 2022 Request for Information Reclamation and Vegetation
Arrow Field Services, LLC
10-Inch and 8-Inch Pipeline Project
Case No. PU-17-48

Dear Mr. Fahn,

Arrow Field Services, LLC corrected the lone issue documented by the Commission's third-party inspection report and filed on September 12, 2019 (<https://psc.nd.gov/database/documents/17-0048/057-010.pdf>). The minor rill erosion in 2019 has been addressed. Fertilizer, gypsum, and weed-free mulch were incorporated into the topsoil and seeded with a native seed mix (based upon NDSU recommendations) as well as a sterile Oats cover crop. Attached is an image of the area immediately after reclamation activities occurred. Please note the area of concern which was addressed is located on a parcel of land owned by Arrow Field Services, LLC.

Respectfully,

A handwritten signature in black ink, appearing to read 'Josh Swann', written over a horizontal line.

Josh Swann
Environmental Construction Manager
(701) 675 8628
Josh.Swann@Crestwoodlp.com

Date & Time: Tue, Jul 19, 2022, 09:56:05 CDT
Position: 047.692308° N / 103.254924° W (± 15.1 ft)
Altitude: 2249ft (± 11.7 ft)
Datum: WGS-84
Azimuth/Bearing: 086° N86E 1529mils True ($\pm 19^\circ$)
Elevation Angle: -13.7°
Horizon Angle: $+00.5^\circ$
Zoom: 0.5X



Figure 1: Area documented in the report filed September 12, 2019 has been remedied by fixing erosion, applying soil amendments, and seeding the area.