

Cenex Pipeline Spill History 1990 to Present

PU-17-97

Date	Pipeline	Location	Location Description	Product	Vol. Spilled (gal)	Cause	Cause Category	Reported To:	Comments
7/12/1993	Cenex	NW1/4 Sec. 17, T1N, R27E Section 14	Lockwood--Johnson Lane	diesel & gasoline		deterioration-type failure in pipe wall (probably manufacturing defect)	outside force damage--3rd party	MDEQ	Soil removal was conducted.
10/4/1995	Cenex	T152N, R93W	4 miles west of Newtown, ND	UL gasoline	47712	line hit by contractor for state of North Dakota	outside force damage--3rd party	DOT	Soil removal was conducted.
12/11/1995	Cenex		Laurel	UL gasoline	630	line hit by contractor installing fiber optic communication cable on refinery property	outside force damage--3rd party	DOT	Soil removal was conducted.
9/20/2002	Cenex	N47 097, W1104, 767	Glendive 7 Mi. Cr.	UL gasoline	41874	damage from drilling for replacement of pipe	outside force damage--3rd party	DOT	Soil removal was conducted.
9/1/2006	Cenex	N46deg 42.602min, W105deg 26.986min	MP 191	diesel	42		Equipment	DOT	This was a historic leak that was found when digging up an ILI anomaly, which was an old welded patch. Soil removal was conducted.
Mar. 2007	Cenex		Billings Post Office	diesel					
8/29/2007	Cenex	N45 8352453, W108 372207	MP 24	diesel	2	burn through during in-service welding on a mechanical sleeve		MDEQ	
9/7/2010	Cenex	N46 71782754 deg, W105 44129948 deg	MP 191 receiver	diesel	151	failed internal seal on pressure indicator	Equipment Failure	DOT	Soil removal was conducted.
2/24/2012	Cenex	46 24913, -106 81986	MP 111 BV Upstream Flange	Diesel	7686	Flange Gasket Leak	Equipment Failure	DOT/NRC	Soil removal was conducted.
7/9/2013	Cenex		MP 81	gasoline	36 540	Third party excavator damaged pipeline	Equipment Failure	DOT/NRC	Soil removal was conducted.
12/9/2013	Cenex		Whoopup Creek Road west of Glendive	gasoline/diesel				MDEQ	This was a historic leak that was found when digging up an ILI anomaly, which was an old welded patch. There was evidence of a previous soil removal.
3/28/2017	Cenex		BV 251 S Minnot to Fargo	gasoline/diesel		Failed underground valve fitting	Equipment Failure	DOT/NRC	Soil removal was conducted.
6/7/2017	Cenex		BV 185 Minnot to Fargo	gasoline/diesel		Failed underground valve fitting	Equipment Failure	DOT/NRC	Soil removal was conducted.