

Casey A. Furey
100 West Broadway, Suite 250
P.O. Box 2798
Bismarck, ND 58502-2798
701.223.6585
cfurey@crowleyfleck.com

November 18, 2019

Via USPS and Electronic Mail

Mr. Steve Kahl
Executive Director
North Dakota Public Service Commission
600 E. Boulevard, Dept. 408
Bismarck, ND 58505-0480

Email: ndpsc@nd.gov

In re: Cenex Pipeline, LLC
Case No. PU-17-097
Our File No. 020836-000001

Dear Mr. Kahl:

On November 11, 2019, Cenex Pipeline, LLC notified Commission staff of an on-site injury that occurred on November 10, 2019. Enclosed for filing in the above-referenced matter, are one original and seven copies of Cenex Pipeline, LLC's formal Notification of On-Site Injury regarding the November 10th incident.

Please feel free to contact me with any questions.

Sincerely,

Casey A. Furey

Enc.

cc: Patrick Fahn (via email)
Kari Carter (via email)
Robb Schwend (via email)

**STATE OF NORTH DAKOTA
PUBLIC SERVICE COMMISSION**

**Cenex Pipeline, LLC
10” Refined Fuels Pipeline
Williams, Mountrail, Ward Counties**

Case No. PU-17-097

CENEX PIPELINE, LLC NOTIFICATION OF ON-SITE INJURY

Event Summary

On November 10, 2019 a Loenbro employee was walking to retrieve a tool from their toolbox. As they walked to the location of the tool, the employee slipped and fell to the ground injuring their leg. Following the incident, the onsite foreman was notified, who then contacted the onsite safety representative. The employee was immediately taken to a clinic where x-rays found the left fibula to be fractured. The employee was placed in a medical boot and given crutches.

Corrective Actions

Following the event, Loenbro discussed safety measures with employees to avoid future reoccurrences of injuries, including: a) notification procedures in the event of changes to the condition of the work site; b) stop work authority and appropriate communication channels to report unsafe acts or unsafe working conditions; c) machinery safety; d) use of proper lighting to perform work; and, e) general employee and work area safety considerations such as maintaining awareness of site conditions, avoiding walking around or near moving equipment and vehicles, appropriate use of safety straps/ropes, weather appropriate work gear etc.