

**Fahn, Patrick J.**

---

**From:** Fahn, Patrick J.  
**Sent:** Tuesday, September 21, 2021 9:43 AM  
**To:** Gludt, Tyler  
**Subject:** RE: PU-18-072 - Andeavor Field Services LLC  
**Attachments:** Andeavor route changes exceeding 20 feet.pdf

Tyler, during our call I stated that I could provide a list of locations where Andeavor's as-built route deviates from the Commission designated route by more than 20 feet. The list is attached.

Patrick Fahn  
Director, Public Utilities Division  
North Dakota Public Service Commission  
701-328-4077  
[pfahn@nd.gov](mailto:pfahn@nd.gov)

---

**From:** Gludt, Tyler <TGludt@fredlaw.com>  
**Sent:** Tuesday, September 21, 2021 7:26 AM  
**To:** Fahn, Patrick J. <pfahn@nd.gov>  
**Cc:** Bender, Lawrence <LBender@fredlaw.com>  
**Subject:** PU-18-072 - Andeavor Field Services LLC

**\*\*\*\*\* CAUTION:** This email originated from an outside source. Do not click links or open attachments unless you know they are safe. **\*\*\*\*\***

Good Morning Pat:

Thank you for taking the time last week to discuss with Lawrence and I the Commission's position regarding route deviations. During our call, you indicated that you would be willing to share maps which identify the locations of the route deviations of Andeavor's as-built pipelines in this case. Please advise if you are able to e-mail said maps to us or if we are able to pick up hard copies at the Commission's office.

Thank you,

Ty

**Tyler J. Gludt** | Attorney | Fredrikson & Byron, P.A. | 1133 College Drive, Suite 1000 | Bismarck, ND 58501 | **701.221.8724 (direct)**  
| 701.221.8700 (main) | 701.221.8750 (fax)

*\*\*This is a transmission from the law firm of Fredrikson & Byron, P.A. and may contain information which is privileged, confidential, and protected by the attorney-client or attorney work product privileges. If you are not the addressee, note that any disclosure, copying, distribution, or use of the contents of this message is prohibited. If you have received this transmission in error, please destroy it and notify us immediately at our telephone number (612) 492-7000. The name and biographical data provided above are for informational purposes only and are not intended to be a signature or other indication of an intent by the sender to authenticate the contents of this electronic message.\*\**

95 PU-18-72 Filed 09/21/2021 Pages: 4  
Email attaching list of as-built route deviations more than 20 feet  
<sup>1</sup> Public Service Commission Staff  
Patrick Fahn

Route changes greater than 20 feet from designated route				
North segment			PU-18-72	
Township	Range	Section		
151	98	35		deviation exceeds 20 feet in 1 location
151	98	36		deviation exceeds 20 feet in 1 location
150	98	1		deviation exceeds 20 ft in 3 locations
150	98	12		deviation exceeds 20 feet in 1 location
150	98	13		deviation exceeds 20 feet in 1 location
150	98	24		deviations exceed 20 feet in 3 locations
150	98	23		deviation exceeds 20 feet in 1 location
150	98	26		deviation exceeds 20 feet in 1 long location
150	98	35		deviation exceeds 20 feet in 1 location
149	98	2		deviations exceed 20 feet in 3 locations
149	98	11		deviation exceeds 20 feet in 1 location
149	98	14		deviations exceed 20 feet in 2 locations
149	98	15	covered by April 12, 2021 certification	deviation outside the designated corridor
149	98	22	covered by April 12, 2021 certification	deviation outside the designated corridor
149	98	21	covered by April 12, 2021 certification	deviation outside the designated corridor
149	98	28		deviations exceed 20 feet in 2 locations
149	98	29		deviation exceeds 20 feet in 1 long location
149	98	30		deviation exceeds 20 feet in 1 location
South segment			PU-18-72	
Township	Range	Section		
142	99	3	northernmost location covered by April 12, 2021 certification	deviations exceed 20 feet in 3 locations, 1 location is outside the designated corridor
142	99	10		deviation exceeds 20 feet in 1 location

142	99	15		deviation exceeds 20 feet in 1 location
142	99	22		deviation exceeds 20 feet in 1 location
142	99	27		deviation exceeds 20 feet in 1 location
142	99	34	middle location covered by August 6, 2021 certification	deviations exceed 20 feet in 3 locations
141	99	3		deviation exceeds 20 feet in 1 location
141	99	10		deviations exceed 20 feet in 2 locations
141	99	15		deviations exceed 20 feet in 2 locations
141	99	22		deviations exceed 20 feet in 3 locations
141	99	27		deviations exceed 20 feet in 4 locations
141	99	34	the deviation outside the corridor (south portion) is covered by April 12, 2021 certification	deviations exceed 20 feet in 2 locations, 1 is outside corridor
140	99	6	covered by April 12, 2021 certification	deviation exceeds 20 feet in 1 location, that location is outside corridor
140	99	7		deviation exceeds 20 feet in 1 location
140	99	18		
140	99	19		deviation exceeds 20 feet in 1 location
140	99	30		deviation exceeds 20 feet in 1 location
140	99	31		deviation exceeds 20 feet in 1 location
139	99	6		deviation exceeds 20 feet in 1 location
139	99	7		deviation exceeds 20 feet in 1 long location
139	99	8		deviation exceeds 20 feet in 1 long location
139	99	17		deviation exceeds 20 feet in 1 long location
<b>Transfer segment</b>			PU-18-72	
<b>Township</b>	<b>Range</b>	<b>Section</b>		
139	99	17		deviation exceeds 20 ft for all four lines

139	99	18		deviation exceeds 20 feet in 1 location
139	100	13		deviation exceeds 20 feet in 1 location
139	99	12		deviation exceeds 20 feet in 1 location
139	99	11	covered by August 6, 2021 filing	outside the designated corridor
139	100	10	covered by August 6, 2021 filing	outside the designated corridor