

Crockford, Konrad S.

From: KURT STELLRECHT <stellartr@msn.com>
Sent: Friday, May 20, 2022 09:05
To: Crockford, Konrad S.
Subject: Fw: Photos 2

***** **CAUTION:** This email originated from an outside source. Do not click links or open attachments unless you know they are safe. *****

Morning Konrad,

Not that noticeable, but in 1st pic there are 2 red dots on the power lines that we hit probably 20-30 ft away, so someone had located these lines before or had attempted to. From my perspective it was when gas came in to the bldg you can see where they cut out a sq to locate it. Beside the pt , power lines not located , someone needs to locate the line , either xcell , the owner , or contractor. I have numerous thoughts on this , First off Safety, I have no idea if there are High voltage breakers involved , either at the transformer or the transition box or at the meter box at the bldg. some kind of trip switch , still someone will get hurt.

ND ONE CALL should have a notification sent out to the owner if it is really their power line. They should be registered with state one call if this is the case and notified each time a locate tk comes in that area. Really hard to point a finger at the owner of the bldg if they are unaware that work is taking place around (their power line) . I can go on and on. let me know if you want or need more information.

Have a great weekend

Kurt Stellrecht
Stellar Trenching Inc.
701-232-2699 (O)
218-790-2699 (C)

From: Joel Rusch <lifesarusch1@gmail.com>
Sent: Friday, May 20, 2022 8:14 AM
To: stellartr@msn.com <stellartr@msn.com>
Subject: Photos







Sent from my iPhone





