



FW: Rev. 36 to KRSB-8603 Clean copy issues.

From Kuzara, David <DKuzara@westmoreland.com>

Date Mon 6/1/2026 2:49 PM

To Emmer, Jonathan W. <jemmer@nd.gov>; Johnson, Monty L. <moljohnson@nd.gov>; Ripplinger, Preston <pripplinger@nd.gov>

Cc Sundsbak, Rylan <RSundsbak@westmoreland.com>; Ore, Juris <jore@westmoreland.com>

******* CAUTION:** This email originated from an outside source. Do not click links or open attachments unless you know they are safe. *********

Good afternoon, Jonathan

A revised clean copy of KRSB-8603 has been submitted via Dropbox. Following is also a link. This update has been provided based on the comments below from Preston.

Please do not hesitate to contact me should you have any questions.

Thanks,
Dave

<https://www.dropbox.com/t/g5sjYoCE18YLYsF6>

From: Sundsbak, Rylan <RSundsbak@westmoreland.com>

Sent: Monday, June 1, 2026 7:26 AM

To: Kuzara, David <DKuzara@westmoreland.com>

Subject: FW: Rev. 36 to KRSB-8603 Clean copy issues.

Dave,

Preston brought up a few issues with the clean copy when he was on inspection last week.



Westmoreland Beulah Mining LLC

Rylan Sundsbak

Site Manager

6204 13th St SW, Beulah, ND 58523

Direct: (701) 380-9158 | Mobile: (701) 721-6318

Email: rsundsbak@westmoreland.com | Website: www.westmoreland.com

From: Ripplinger, Preston <pripplinger@nd.gov>

Sent: Thursday, May 28, 2026 10:47 AM

To: Sundsbak, Rylan <RSundsbak@westmoreland.com>

Subject: Rev. 36 to KRSB-8603 Clean copy issues.

39 RC-25-213 Filed 06/01/2026 Pages: 2
Revision 36 Clean Copy Revised Email

Westmoreland Beulah Mining LLC
David Kuzara

This message is from an EXTERNAL SENDER – please use CAUTION, do not click or open unexpected links or attachments.

Rylan,

Here is the list of items that need to be fixed and then please resubmit the clean copy. Any questions feel free to let me know.

Please provide or fix links to the following bookmarks and exhibits:

Section 1.1 – fix bookmark links to the Revision 36 information

Section 1.4 – fix links in the bookmarked sections of Section 1.4

Section 3.8 – fix link to exhibit 3.8.3, Leveling Timing Map

Section 3.8 – fix link to exhibit 3.8.4, Soil Replacement Timing Map

The Listing of Revised Information on page 79 of Section 1.1 Narrative states pages 1.4.61-1.4.67 were updated but Section 1.4 only contains 59 pages. Also, the Listing of Revised Information states that page 2.7.73 was updated but Section 2.5 only contains 72 pages.

The Listing of Revised Information states that Table 2.2.12 was updated under Section 2.5. Table 2.2.12 should be Table 2.5.12.

Thanks,

Preston Ripplinger

Geologist/Hydrologist

ND Public Service Commission

Reclamation Division

600 E. Boulevard Ave. Dept. 408

Bismarck ND 58505-0480

P: 701.328.2251

Email: priplinger@nd.gov



This transmission, email and any files transmitted with it, may be: (1) subject to the Attorney-Client Privilege, (2) an attorney work product, or (3) strictly confidential under federal or state law. If you are not the intended recipient of this message, you may not use, disclose, print, copy or disseminate this information. If you have received this transmission in error, notify the sender (only) and delete the message. This message may also be subject to disclosure under the North Dakota Open Records Laws.