


Enbridge Pipelines (North Dakota) LLC
 2505 16th Street S.W.
 Minot, ND 58701-6947
 United States
www.enbridge.com

Brent J. Horton
 Supervisor – Special Projects
 Tel: 701-857-0810
 Fax: 701-857-0809



File: 03.02.b

September 1, 2006

Ms. Illona A. Jeffcoat-Sacco
 Executive Secretary
 North Dakota Public Service Commission
 600 E. Boulevard Ave., Dept. 408
 Bismarck, ND 58505-0480

Dear Ms. Jeffcoat-Sacco:

**RE: Enbridge Pipelines (North Dakota) LLC (“Enbridge”)
 North Dakota Public Service Commission
 For a Certificate of Corridor Compatibility and a Route Permit
 For the Trenton to Beaver Lodge Line Loop
 Case No. PU-06-330**

At the hearing held on August 28, 2006, a request was made by the Commission to provide a report to the Commission of any accidents that may have occurred to the pipeline which was constructed in 1983 under a prior Commission order.

Enbridge has reviewed its corporate records pertaining to the 1983 pipeline and has found no indication of any accidents resulting in any leaking of crude oil since the original in-service date.

We hope that this letter sufficiently responds to the inquiry of the Commission in this regard.

Yours truly,

Brent J. Horton
 Supervisor – Special Projects