




**STATE
HISTORICAL
SOCIETY
OF NORTH DAKOTA**



John Hoeven
Governor of North Dakota

North Dakota
State Historical Board

Marvin L. Kaiser
Williston - President

Albert I. Berger
Grand Forks - Vice President

Chester E. Nelson, Jr.
Bismarck - Secretary

Gereld Gertholz
Valley City

A. Ruric Todd III
Jamestown

Diane K. Larson
Bismarck

John E. Von Rueden
Bismarck

Sara Otte Coleman
*Director
Tourism Division*

Kelly Schmidt
State Treasurer

Alvin A. Jaeger
Secretary of State

Douglass Prchal
*Director
Parks and Recreation
Department*

Grant Levi
*Interim Director
Department of
Transportation*

Merlan E. Paaverud, Jr.
Director



Accredited by the
American Association
of Museums

October 6, 2006

Public Service Commission
600 East Boulevard Avenue, Dept. 408
Bismarck, ND 58505-0480

Ms. Jennifer Turnbow
Kadmas, Lee and Jackson, Inc.
PO Box 1157
Bismarck, ND 58501

ND SHPO Ref.: 07-0013A Enbridge Pipelines (North Dakota) LLC, Phase 4 Pumping Stations, Grand Forks, McHenry, Mountrail, and Ramsey Counties, North Dakota

Dear Sirs,

We reviewed Duane Klinner and John G Morrison's "Enbridge Pipelines (North Dakota) LLC, Phase 4 Pipeline Expansion Project Pumping Stations: A Class III Cultural Resource Inventory, Grand Forks, McHenry, Mountrail, and Ramsey Counties, North Dakota," and find the report acceptable. We concur with a "No Historic Properties Affected" determination, provided that the projects are of the nature specified and take place in the legal descriptions outlined and mapped in the report, and with the following stipulations:

- That any borrow fill material, such as dirt, rock or gravel come from an approved source, that is a source evaluated by a qualified Archaeologist and found to contain no significant cultural resources.
- That three architectural sites, including their landscape features, be avoided by the project, 32RY465, 32RY361 grain elevator, and 32RY362. These sites should be evaluated by a qualified Architectural Historian before any work is done to the buildings or to their landscape features. In lieu of evaluation by a qualified Architectural Historian before destruction, site 32RY465 can be photographed in a more complete manner, with historic documentation to follow.

Thank you for the opportunity to review these projects. Please include the ND SHPO Reference number listed above in any further correspondence for this specific project. If you have any questions please contact Susan Quinnell, Review and Compliance Coordinator at (701) 328-3576, or squinnell@nd.gov

Sincerely,

Merlan E. Paaverud, Jr.
State Historic Preservation Officer (North Dakota)
and
Director, State Historical Society of North Dakota

c: Earthworks, 128 Soo Line Drive, Bismarck, ND 58501