

Fahn, Patrick J.

From: Todd Kranda [kranda@kelschlaw.com]
Sent: Thursday, February 05, 2009 5:21 PM
To: Fahn, Patrick J.
Cc: -Grp-PSC Commissioners; mark.anderson@kljeng.com
Subject: RE: sink holes at Pembina River HDD site

Mr. Pat Fahn – As you may already be aware, TransCanada Keystone Pipeline has taken immediate steps to ensure safety and continues to monitor and make additional notifications regarding the situation. TransCanada is consulting with geologists to evaluate the best options to restore the void and has dispatched a geotechnical engineer to the site today. I will try keep you advised as soon as I have any information about the mitigation plan and time frame for completion. In the meantime, TransCanada has been in contact regarding this situation with the Inspector from Kadrmas Lee & Jackson who was appointed by the PSC. Also, TransCanada has notified the landowner (ND State Parks), has notified the local recreation club who uses the area, and has erected barricades and put signs in place. Todd D. Kranda

From: Fahn, Patrick J. [mailto:pfahn@nd.gov]
Sent: Thursday, February 05, 2009 10:13 AM
To: Todd Kranda
Cc: -Grp-PSC Commissioners; mark.anderson@kljeng.com
Subject: sink holes at Pembina River HDD site

Mr. Kranda,
I have attached the most recent 3rd party inspector reports including pictures that relay a condition of several large sink holes at the Pembina River HDD site. Please ask TransCanada to provide its mitigation plan, the timeline for the mitigation and describe any measures that will be taken in the interim.

Patrick Fahn
Director-Compliance and Competitive Markets
Email: pfahn@nd.gov
Phone: (701) 328-4077

North Dakota Public Service Commission
600 E Boulevard
Bismarck ND 58505-0480
Fax: (701) 328-2410