

PSC CASE NUMBER: PU-06-421

Kadrmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT

1 / 3

Job Site: North Spread

Date: Sept 5, 2009

Location and

Operations Observed:

Mi. 33	completed restoration
Mi. 34	Pipeline Tie-In
Mi. 36	} various stages of restoration.
Mi. 37	
Mi. 38	
Mi. 39	
Mi. 40	
Mi. 41-42	

General Notes:

Mi 33 - Restoration work appears complete. No subsidence observed. Field is level. Rocks have been picked ... the cover crop is emerging

Mile 34
Again the restoration work looks to be complete. I observed crews working on the Edinburg Pump Station. Contractor (Henkels) & McCoy are busy with a pipe & valve tie in to the Pump Station. Embankment excavated for pipe has been placed adjacent to the pipe and has been surrounded with silt fence, in accordance with

Kadrmass
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 9-5-2009

Page 2 of 3

specifications to prevent any run-off from entering the adjacent coulees.

Mile 36 Restoration work includes field leveling, rock picking & seeding / w/ straw mulch, the disturbed Right of Way along Walsh County Highway # 9, west of Edinburg.

Mile 37 Right of way corridor has been leveled and seeded. No cover has emerged yet. No subsidence observed.

Mile 38 No subsidence observed. Field leveled and seeded. Cover crop well emerged on North end of this mile, recently seeded on south end.

Mile 39 Cover crop growing actively..... No subsidence noted. Field clean of rock.

Mile 40 - Restoration looks good

Mile 40-41-42 Construction corridor has been leveled and rocks picked through this rolling hill area. Rice cover crop emerging on North end. Silt bars have been effective in controlling erosion down hills leading to pasture. May need to reseed south end of this mile due to weeds.

PSC CASE NUMBER: PU-06-421

Kadmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 9-5-09

Page 3 of 3

The following deviations from the finding of facts were found:

- None observed -

Signature:

Dennis Markusen

Print Name:

Dennis Markusen

