

215 South Cascade Street  
PO Box 496  
Fergus Falls, Minnesota 56538-0496  
218 739-8200  
www.otpc.com (web site)

RECEIVED

JUL 01 2008

PUBLIC SERVICE COMMISSION



July 2, 2008

Mr. Jerry Lein  
North Dakota Public Service Commission  
600 E. Boulevard, Dept. 408  
Bismarck, ND 58505-0480

RE: Pillsbury – Fargo Generation Outlet

Dear Jerry,

I have enclosed two colored copies of the plan-profile sheets for Section 2 (Structures 141-242) and Section 3 (Structures 243-313) for your review. The electronic version was sent to you and also to the nd.gov site on July 1 by Duane Phillips of Stanley Consultants.

Please let me know if you have any questions or need further information.

Sincerely,

A handwritten signature in black ink, appearing to read "Todd Langston".

Todd Langston  
T-Line Construction Manager  
Otter Tail Power Company  
218-739-8679  
C-218-770-6376

73 **PU-08-48** Filed: 7/3/2008 Pages: 25  
Plan Profile Sheets for Section 2 and Section 3

Otter Tail Corporation



# **Wind Generation Tie 230 kV Transmission Line**

Sections 2 & 3 Structure 142 –313

Plan – Profile

**Minnkota Power Cooperative**