



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Mr. David J. Nilson  
Reclamation Administrator  
Basin Cooperative Services  
Leland Olds Station  
3901 Hwy 200A  
Stanton, ND 58571

Dear Mr. Nilson:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application Number 1 to Surface Coal Mining Permit BCGH-8801 at the Glenharold Mine. **We will meet at the Glenharold Mine office at 10:00 a.m., CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008, to begin the inspection.** Surface owners, County Commissioners, and others will be invited to attend.

If you have any questions, please contact this office.

Sincerely,

*for* James R. Deutsch  
Director  
Reclamation Division

m:\glenharold\8801\Bond Release\No. 1\inspection\_ltrs\_8-28-08



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Bryan Reinhardt  
2901 SE 46<sup>th</sup> Ave  
Mandan, ND 58554

Dear Mr. Reinhardt:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. As a surface owner, you are welcome to participate in the bond release inspection. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m., CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.**

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

A handwritten signature in black ink that reads "Dean K. Moos".

for James R. Deutsch  
Director  
Reclamation Division



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Duane and Marilyn Reinhardt  
1925 Cottontail Drive  
Beulah, ND 58523

Dear Mr. & Mrs. Reinhardt:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. As a surface owner, you are welcome to participate in the bond release inspection. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m., CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.**

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

*for* James R. Deutsch  
Director  
Reclamation Division



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Mr. Terry Steinwand, Director  
North Dakota Game and Fish Department  
100 North Bismarck Expressway  
Bismarck, ND 58505

Dear Mr. Steinwand:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. You or your representatives are invited to participate in the bond release inspection. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m. CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.** The acreage included in this bond release application consists primarily of reclaimed native grassland and woodlands.

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

A handwritten signature in black ink that reads "Dean K. Moos".

*for* James R. Deutsch  
Director  
Reclamation Division



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Mr. Larry Kotchman  
State Forester  
N.D. Forest Service  
307 1<sup>st</sup> Street East  
Bottineau, ND 58318

Dear Mr. Kotchman:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. You or your representatives are invited to participate in the bond release inspection. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m. CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.** The acreage included in this bond release application consists primarily of reclaimed native grassland and woodlands.

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

for James R. Deutsch  
Director  
Reclamation Division



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Mr. Scott Hochhalter  
State Soil Conservation Committee  
2718 Gateway Ave., Unit #104  
Bismarck, ND 58503

Dear Mr. Hochhalter:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. You or your representatives are invited to participate in the bond release inspection. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m. CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.** The acreage included in this bond release application consists primarily of reclaimed native grassland and woodlands.

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

for James R. Deutsch  
Director  
Reclamation Division



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Mr. Jeffrey Towner  
U.S. Fish and Wildlife Service  
3425 Miriam Avenue  
Bismarck, North Dakota 58501-7926

Dear Mr. Towner:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of private land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. You are invited to participate in the bond release inspection to see and evaluate reclaimed native grassland and woodlands. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m. CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.**

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

A handwritten signature in black ink that reads "James R. Deutsch".

*for* James R. Deutsch  
Director  
Reclamation Division



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008\

Oliver County Commissioners  
PO Box 188  
Center, ND 58530

Dear Commissioners:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. You or your representatives are invited to participate in the bond release inspection. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m. CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.** The acreage included in this bond release application consists primarily of reclaimed native grassland, woodlands and a few acres of cropland. There are no county roads in this bond release. The surface is owned by Basin Cooperative Services and Duane/Marilyn/Bryan Reinhardt.

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

for James R. Deutsch  
Director  
Reclamation Division



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

Mr. Jeffery Printz  
State Rangeland Management Specialist  
Natural Resource Conservation Service  
PO Box 1458  
Bismarck, ND 58502-1458

Dear Mr. Printz:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of private land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. You or your representatives are invited to participate in the bond release inspection to see and evaluate reclaimed native grassland and woodlands. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m. CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.**

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

for James R. Deutsch  
Director  
Reclamation Division

CC: Craig M. Stange, NRCS State Forester, (same address as above)  
Lee O. Voigt, NRCS Area II, Rangeland Management Specialist, Jamestown Area  
Office, 208 2<sup>nd</sup> Ave. SW, PO Box 2096, Jamestown, ND 58402-2096



# Public Service Commission

## State of North Dakota

---

### COMMISSIONERS

Susan E. Wefald, President  
Kevin Cramer  
Tony Clark

Executive Director  
Illona A. Jeffcoat-Sacco

600 E. Boulevard Ave. Dept 408  
Bismarck, North Dakota 58505-0480  
web: [www.nd.gov/psc](http://www.nd.gov/psc)  
e-mail: [ndpsc@nd.gov](mailto:ndpsc@nd.gov)  
TTY 800-366-6888 or 711  
Fax 701-328-2410  
Phone 701-328-2400

August 28, 2008

David D. Pfliiger  
District Conservationist  
NRCS Center Field Office  
345 Center Avenue South, Box 87  
Center, ND 58436-0087

Dear Mr. Pfliiger:

The Reclamation Division has scheduled a field inspection for Final Bond Release Application No. 1 to Surface Coal Mining Permit BCGH-8801 at Basin Cooperative Services (BCS) Glenharold Mine. The bond release application involves 846.56 acres of private land located in Sections 16, 17 and 21 of T143N, R84W, Oliver County. You or your representatives are invited to participate in the bond release inspection to see and evaluate reclaimed native grassland, woodlands and cropland. We will meet at the Glenharold Mine office located on the south side of Highway 200A, southwest of the Leland Olds (LOS) Power Plant at **10:00 a.m. CDT (9:00 MDT) on Tuesday, September 9<sup>th</sup>, 2008 to begin the inspection.**

Please contact Guy Welch at 701-328-2298 if you are planning to attend so that you can be contacted in case of cancellation or delay. If you have any questions, please contact this office.

Sincerely,

A handwritten signature in black ink that reads "James R. Deutsch".

*for* James R. Deutsch  
Director  
Reclamation Division