

Bison I Wind
PU-09-151
Week Ending 7-17-2010

O&M Bldg:

- Banding and Roofing (Shop of O&M Building) [Northwest]
- Stud Walls (Office of O&M Building) [Northwest]
- Fire Wall (Between Office & Shop of O&M Building) [Northwest]
- Install Hollow Metal Door Frames (Office of O&M Building) [Northwest]
- Plumbing Rough-In (Office of O&M Building) [Northwest]
- Electrical Rough-In (Office of O&M Building) [Michels]
- Electrical Service Install (Shop of O&M Building) [Michels]

Balance of Plant [Michels]:

- Cut/Fill on 31st St
- Cut/Fill on 51st Ave
- Place Class 13 on 31st St and 52nd Ave
- Silt Fence Installations on Turbine Sites
- Culvert Installation on 31st St & 50th Ave
- Received (9) additional GSU Transformers

230 KV Bison Substation:

- PROLEC removed defective radiator on PROLEC XFMR G – 2484 and replaced it with a new unit.
- HOOPER began Bison substation steel erection.
- HOOPER continued to make progress on underground conduits, ground grid and cable raceway.