

# Center to Grand Forks Project



## ► CGF Project Weekly Status Report

Case No. PU-09-670

Michael Hennes ► Minnkota Power Cooperative, Inc. ► 11/26/2013

Week 82

Extraordinary Events

Safety: Construction Equipment – No Injury Incident

Environmental: Minor

Damage: None

Threatened or endangered Species: None

Cultural or Historical: None

Attachments: None

Construction Summary To-Date:

Foundations Installed = 1205

Structures Set = 1080

Spans of Conductor Pulled = 859

# CGF Project Weekly Status Report

Case No. PU-09-670

## Safety/Damages

- A contractor owned semi hauling 2 casings hit some ice, lost control and rolled at the intersection of Hwy 200 & Hwy 41 in Mercer, ND. No other vehicles were involved and there were no injuries.
- During excavation at structure 254, an underground power line was identified and exposed – no damage, outage, or injuries occurred.

## Environmental

A bison rib-bone was found during excavation of structure 69R. Work was stopped; the site monitor called back, and a determination was made that no additional actions were required and work was resumed.

## Work Progress

Survey: Const. Stake: 135-142, 162-164, 247, 255, 261, 281 ESA/ROW: 22-26, 127-128, 130-138 QC: 162-164, 247, 255, 261, 281

Material delivery continues with deliveries of structures and materials to AI-Center. One (1) load to AI-Center.

Foundation installation has completed structures 71, 254, 265, 270-271, 273-274, 283, 287-289, 292, 749-750, 752-756 and 765-766 over the past week for a total of 21 whole foundations, with 1,205 completed in total.

Line construction crews performed structure setting at 91, 99, 115 and 333-342 over the past week for a total of 12 structures, with 1,080 completed in total.

Wire stringing: Clipped Conductor: 206-207, 352-371 OHPGW: 199-210, 518-523 OPGW: 197-209

Restoration: CI Yard, 645-647, 678-680, 728-729, 742

## Work Planned for Next Week

Foundation installation of structures: 151, 248-250, 252-253, 257-259, 261-262

Structure setting: 332-308, 281-279, 266

Wire Stringing: Conductor 322-251, 232-210, 199-172. OPGW 498-478. OHGW 512-460.

Restoration: Fix ruts in the Alkali Flats.

## Land Owner/Public Issues

None

## Cultural or Historical Events

None

## Extraordinary Events

A single vehicle accident as reported in the Safety section. There were no injuries associated with this incident.

## Structure Move Requests

None.