

Bison 2 Weekly Construction Report
PU-11-57
Week Ending: 10/01/11

Construction

Alignment	Topsoil stripped	Subgrade	Gravel	Topsoil Respread	Turf Established
A1	x	x			
A5	x	x			
A6	x	x	x		
A7	x	x	x		
B1	x	x	x		
B2	x	x			
B3	x	x	x		
C	x	x			
D	x	x	x		
E	x	x	x		
F	x	x	x		
G	x	x	x		
H	x				
I1	x	x			
I2	x	x			
J1					
J2					
K	x	x	x		
L1	x	x	x		
L2	x	x	x		
M	x	x	x		

- Foundations
 - Embed, Rebar and Anchor Bolt deliveries are in process
- Collections
 - Trenching 808 Circuit
 - Trenching 809 Circuit

Misc.

- Circuits 809 and 812 are staked

Weather Impacts

- None

Manpower on Site

- Michels - 70
- Braun - 1 full time
- MP - 4