



Public Service Commission
State of North Dakota

COMMISSIONERS

Randy Christmann
Julie Fedorchak
Brian Kroshus

Executive Secretary
Darrell Nitschke

September 26, 2017

600 East Boulevard, Dept. 408
Bismarck, North Dakota 58505-0480
Web: www.psc.nd.gov
E-mail: ndpsc@nd.gov
Phone: 701-328-2400
ND Toll Free: 1-877-245-6685
Fax: 701-328-2410
TDD: 800-366-6888 or 711

Casey A. Furey
Crowley Fleck Attorneys PLLP
100 West Broadway, Suite 250
P.O. Box 2798
Bismarck, ND 58502-2798

**Re: Case No. PU-16-42, Brady Wind II, LLC
Brady II Wind Energy Center – Hettinger & Stark**

The North Dakota Public Service Commission retained Keitu Engineers & Consultants, Inc. as a third-party vendor to provide construction inspection services in the above-referenced case. A copy of the As-Built Inspection Report filed by Keitu as well as the Commission's Order in this proceeding is accessible through the Commission's website at the following links:

As-Built Inspection Report:

<https://psc.nd.gov/database/documents/16-0042/124-020.pdf>

Commission Order:

<https://psc.nd.gov/database/documents/16-0042/072-030.pdf>

As discussed in the As-Built Inspection Report, there are areas that need attention due to water erosion. Please review picture numbers 1, 2, and 6. Please provide updated pictures of these areas in October in order to ensure that these issues have been corrected.

If you have any questions regarding this letter, please contact me at 701-328-4153.

Sincerely,

Sara Cardwell
Public Utility Analyst