

Exhibit ND-OTP-010-2 Dakota Valley Substation Outage History

Outage Sub	Feeder	Phs	Time Off	Time On	Duration	Type	Cause Desc	# Out	Equip Desc
86693	MOO	99 ABC	5/8/2007 11:40	5/8/2007 12:30	0:50	Substation	POWER SUPPLIER	197	SUBSTATION HIGH SIDE FUSE
165338	MOO	99 ABC	7/17/2011 20:27	7/18/2011 0:39	4:12	Substation	POWER SUPPLIER	218	TRANSMISSION POLE
185230	MOO	99 ABC	5/2/2012 23:52	5/3/2012 1:38	1:46	Substation	POWER SUPPLIER	218	POWER SUPPLIER
220564	MOO	99 ABC	9/22/2014 9:08	9/22/2014 9:25	0:16	Substation	MAINTENANCE PLANNED	228	OH CONDUCTOR

Hours:Minutes