



Public Service Commission

State of North Dakota

COMMISSIONERS

Brian Kroshus
Julie Fedorchak
Randy Christmann

September 25, 2020

600 East Boulevard, Dept. 408
Bismarck, North Dakota 58505-0480
Web: www.psc.nd.gov
E-mail: ndpsc@nd.gov
Phone: 701-328-2400
ND Toll Free: 1-877-245-6685
Fax: 701-328-2410
TDD: 800-366-6888 or 711

Lawrence Bender, Attorney at Law
Fredrikson & Bryon, P.A.
1133 College Drive, Suite 1000
Bismarck, ND 58501-1215

NOTICE OF NONCOMPLIANCE - SUPPLEMENT

RE: Case No. PU-18-72, Andeavor Field Services LLC, 8" & 6" NGL Pipelines
– McKenzie, Billings, Stark Counties

On January 13, 2020, Commission staff issued a Notice of Noncompliance to Andeavor Field Services LLC in the above referenced case.

On October 29, 2019, following completion of the construction of the facility, Wenck Associates, Inc., the Commission's third-party construction inspector, filed an As-Built Inspection Report regarding the pipelines referenced above.

Andeavor did not provide the Commission with as-built maps within 3 months of completion of the construction of the facility. Andeavor is required to file paper, electronic and GIS versions of the as-built maps within 3 months.

On May 11, 2020, Commission staff emailed Andeavor with a reminder to file the as-built maps.

On May 13, 2020, Andeavor filed with the Commission paper versions and electronic versions of as-built survey maps for the pipelines. Andeavor did not file the GIS versions at that time.

On May 14, 2020, Commission staff emailed Andeavor with a reminder to file the GIS version of the as-built maps.

On approximately August 10, 2020, Commission staff received the GIS version of the as-built maps.

Commission staff compared the GIS as-built maps with the GIS of the pipeline route designated by the Commission, Commission staff determined that the as-

86 **PU-18-72** Filed: 9/25/2020 Pages: 2
Notice of Noncompliance - Supplement


built route does not coincide with the route designated by the Commission's June 13, 2018 Findings of Fact, Conclusions of Law and Order.

Of the 17-mile (89,760 feet) North Segment, approximately 2,951.5 feet are on the designated route. Of the 22-mile (116,160 feet) South Segment, approximately 268 feet are on the designated route. Most of the 5-mile Transfer Segment (four pipelines) (26,400 feet) appears to be on the designated route with the exception that all four lines extend approximately 50 feet off the designated route at the east end, and all four lines extend 3,593 feet beyond the west end of the designated route.

Andeavor failed to file with the Commission certifications and supporting documentation required under North Dakota Century Code section 49-22.1-15 before conduction construction activities associated with the route adjustments.

In response to this Notice of Noncompliance - Supplement, Andeavor may provide supplemental information by October 19, 2020.

Best regards,



Patrick Fahn

Director, Public Utilities Division