

Casey A. Furey  
100 West Broadway, Suite 250  
P.O. Box 2798  
Bismarck, ND 58502-2798  
701.223.6585  
cfurey@crowleyfleck.com

November 9, 2022

***Via Hand Delivery & Electronic Mail***

Mr. Adam Renfandt  
Public Utility Analyst  
North Dakota Public Service Commission  
600 E. Boulevard, Dept. 408  
Bismarck, ND 58505-0480  
[arenfandt@nd.gov](mailto:arenfandt@nd.gov)  
[ndpsc@nd.gov](mailto:ndpsc@nd.gov)

**In re: Bridger Pipeline LLC  
16-inch South Bend Crude Oil Pipeline  
Case No. PU-21-048  
Our File No. 016265-000018**

Dear Mr. Renfandt:

I am writing on behalf of Bridger Pipeline LLC (“Bridger”) in response to our conversation regarding Stantec Consulting Services Inc.’s (“Stantec”) September 2022 Construction Report (Docket No. 78) filed in the above-referenced matter. You requested Bridger respond to Stantec’s recommendation for additional erosion-control measures to be implemented along Observation Point 5 at the crossing of Bennie Peer Stream. As we previously discussed, on October 6, 2022, Bridger went onsite to install silt fencing below the pile of stored topsoil to prevent migration and removed migrated silt in accordance with Stantec’s recommendations. This filing is submitted to formally document Bridger’s response and to confirm Bridger previously implemented Stantec’s recommendations at Observation Point 5.

Please feel free to contact me if you have any questions. Thank you.

Sincerely,

*/s/ Casey A. Furey*

Casey A. Furey

cc: Kevin Cook (via email); Matthew Retka (via email)