

# Attachment C – FAA Determination of No Hazard Summary

FAA OE/AAA Determinations  
Rugby Wind Repower

STUDY (ASN)	PRIOR ASN	STATUS	DETERMINATION	COMPLETION DATE	STRUCTURE NAME	AGL HEIGHT PROPOSED
2023-WTE-783-OE	2006-AGL-4320-OE	Determined	No Hazard	4/12/2023	A2	499
2023-WTE-784-OE	2008-AGL-3658-OE	Determined	No Hazard	4/12/2023	A3	499
2023-WTE-785-OE	2008-AGL-3639-OE	Determined	No Hazard	4/12/2023	A4	499
2023-WTE-786-OE	2006-AGL-4323-OE	Determined	No Hazard	4/12/2023	A5	499
2023-WTE-787-OE	2008-WTE-3090-OE	Determined	No Hazard	4/12/2023	A6	499
2023-WTE-788-OE	2006-AGL-4325-OE	Determined	No Hazard	4/12/2023	A7	499
2023-WTE-789-OE	2008-AGL-3649-OE	Determined	No Hazard	4/12/2023	A8	499
2023-WTE-790-OE	2006-AGL-4343-OE	Determined	No Hazard	4/12/2023	B1	499
2023-WTE-791-OE	2008-WTE-3085-OE	Determined	No Hazard	4/12/2023	B2	499
2023-WTE-792-OE	2008-WTE-3086-OE	Determined	No Hazard	4/12/2023	B3	499
2023-WTE-793-OE	2006-AGL-4346-OE	Determined	No Hazard	4/12/2023	B4	499
2023-WTE-794-OE	2006-AGL-4342-OE	Determined	No Hazard	4/12/2023	B5	499
2023-WTE-795-OE	2006-AGL-4347-OE	Determined	No Hazard	4/12/2023	C1	499
2023-WTE-796-OE	2008-WTE-3087-OE	Determined	No Hazard	4/12/2023	C2	499
2023-WTE-797-OE	2008-WTE-3088-OE	Determined	No Hazard	4/12/2023	C3	499
2023-WTE-798-OE	2008-WTE-3089-OE	Determined	No Hazard	4/12/2023	C4	499
2023-WTE-799-OE	2008-AGL-3640-OE	Determined	No Hazard	4/12/2023	D1	499
2023-WTE-800-OE	2008-WTE-3094-OE	Determined	No Hazard	4/12/2023	D2	499
2023-WTE-801-OE	2008-WTE-3095-OE	Determined	No Hazard	4/12/2023	D3	499
2023-WTE-802-OE	2006-AGL-4352-OE	Determined	No Hazard	4/12/2023	D4	499
2023-WTE-803-OE	2006-AGL-4326-OE	Determined	No Hazard	4/12/2023	E1	499
2023-WTE-804-OE	2008-AGL-3641-OE	Determined	No Hazard	4/12/2023	E2	499
2023-WTE-805-OE	2008-AGL-3656-OE	Determined	No Hazard	4/12/2023	E3	499
2023-WTE-806-OE	2008-AGL-3642-OE	Determined	No Hazard	4/12/2023	E4	499
2023-WTE-807-OE	2008-AGL-3657-OE	Determined	No Hazard	4/12/2023	E5	499
2023-WTE-808-OE	2008-AGL-3643-OE	Determined	No Hazard	4/12/2023	F1	499
2023-WTE-809-OE	2006-AGL-4330-OE	Determined	No Hazard	4/12/2023	F2	499
2023-WTE-810-OE	2008-AGL-3644-OE	Determined	No Hazard	4/12/2023	F3	499
2023-WTE-811-OE	2006-AGL-4332-OE	Determined	No Hazard	4/12/2023	G1	499
2023-WTE-812-OE	2008-AGL-3645-OE	Determined	No Hazard	4/12/2023	G2	499
2023-WTE-813-OE	2008-AGL-3646-OE	Determined	No Hazard	4/12/2023	G3	499
2023-WTE-814-OE	2010-WTE-12213-OE	Determined	No Hazard	4/12/2023	G4	499
2023-WTE-815-OE	2006-AGL-4338-OE	Determined	No Hazard	4/12/2023	G5	499
2023-WTE-816-OE	2008-AGL-3648-OE	Determined	No Hazard	4/12/2023	G6	499
2023-WTE-817-OE	2009-WTE-1418-OE	Determined	No Hazard	4/12/2023	G7	499
2023-WTE-818-OE	2006-AGL-4354-OE	Determined	No Hazard	4/12/2023	H1	499
2023-WTE-819-OE	2008-AGL-3654-OE	Determined	No Hazard	4/12/2023	H2	499
2023-WTE-820-OE	2006-AGL-4364-OE	Determined	No Hazard	4/12/2023	J1	499
2023-WTE-821-OE	2006-AGL-4363-OE	Determined	No Hazard	4/12/2023	J2	499
2023-WTE-822-OE	2006-AGL-4362-OE	Determined	No Hazard	4/12/2023	J3	499
2023-WTE-823-OE	2008-AGL-3665-OE	Determined	No Hazard	4/12/2023	J4	499
2023-WTE-824-OE	2006-AGL-4365-OE	Determined	No Hazard	4/12/2023	K1	499
2023-WTE-825-OE	2008-AGL-3655-OE	Determined	No Hazard	4/12/2023	K2	499
2023-WTE-826-OE	2008-AGL-3666-OE	Determined	No Hazard	4/12/2023	K3	499
2023-WTE-827-OE	2009-WTE-7953-OE	Determined	No Hazard	4/12/2023	L1	499
2023-WTE-828-OE	2008-AGL-3661-OE	Determined	No Hazard	4/12/2023	L2	499
2023-WTE-829-OE	2008-AGL-3653-OE	Determined	No Hazard	4/12/2023	L3	499
2023-WTE-830-OE	2006-AGL-4361-OE	Determined	No Hazard	4/12/2023	M1	499
2023-WTE-831-OE	2006-AGL-4360-OE	Determined	No Hazard	4/12/2023	M2	499
2023-WTE-832-OE	2006-AGL-4359-OE	Determined	No Hazard	4/12/2023	M3	499
2023-WTE-833-OE	2006-AGL-4358-OE	Determined	No Hazard	4/12/2023	M4	499
2023-WTE-834-OE	2006-AGL-4357-OE	Determined	No Hazard	4/12/2023	M5	499
2023-WTE-835-OE	2008-AGL-3664-OE	Determined	No Hazard	4/12/2023	M6	499
2023-WTE-836-OE	2008-AGL-3663-OE	Determined	No Hazard	4/12/2023	M7	499
2023-WTE-837-OE	2008-AGL-3671-OE	Determined	No Hazard	4/12/2023	N1	499
2023-WTE-838-OE	2008-AGL-3672-OE	Determined	No Hazard	4/12/2023	N2	499
2023-WTE-839-OE	2008-AGL-3673-OE	Determined	No Hazard	4/12/2023	P1	499

FAA OE/AAA Determinations  
Rugby Wind Repower

2023-WTE-840-OE	2008-AGL-3674-OE	Determined	No Hazard	4/12/2023	P2	499
2023-WTE-841-OE	2008-WTE-3091-OE	Determined	No Hazard	4/12/2023	Q1	499
2023-WTE-843-OE	2008-WTE-3092-OE	Determined	No Hazard	4/12/2023	Q3	499
2023-WTE-842-OE	2008-AGL-3669-OE	Determined	No Hazard	4/12/2023	Q2	499
2023-WTE-844-OE	2009-WTE-3419-OE	Determined	No Hazard	4/12/2023	Q4	499
2023-WTE-845-OE	2008-WTE-3093-OE	Determined	No Hazard	4/12/2023	R1	499
2023-WTE-846-OE	2008-AGL-3677-OE	Determined	No Hazard	4/12/2023	R2	499
2023-WTE-847-OE	2008-AGL-3678-OE	Determined	No Hazard	4/12/2023	R3	499
2023-WTE-848-OE	2008-AGL-3679-OE	Determined	No Hazard	4/12/2023	R4	499
2023-WTE-849-OE	2008-AGL-3681-OE	Determined	No Hazard	4/12/2023	S1	499
2023-WTE-850-OE	2008-AGL-3682-OE	Determined	No Hazard	4/12/2023	S2	499
2023-WTE-851-OE	2008-AGL-3683-OE	Determined	No Hazard	4/12/2023	S3	499
2023-WTE-852-OE	2008-AGL-3684-OE	Determined	No Hazard	4/12/2023	S4	499
2023-WTE-853-OE	2008-AGL-3675-OE	Determined	No Hazard	4/12/2023	S5	499