

Photograph 1. Pipeline ROW at Bemidji (7/30/07)



134 PU-06-421 Filed: 9/5/2007 Pages: 5  
Exhibit T20 Photographs of Bemidji pipeline spill location

TransCanada Keystone Pipeline, LP



Photograph 2. Spray Zone Overview (7/30/07)



**Photograph 3. Hydrophobic soils within Spray Zone showing little revegetation. (07/30/07)**



Photograph 4. North Pool and monitoring wells. (07/30/07)



Photograph 5. Wetland and South Pool (07/30/07).

