

Hamre, John G.

From: Fahn, Patrick J.
Sent: Monday, December 08, 2008 1:42 PM
To: Hamre, John G.
Subject: FW: PSC Project PU-06-421
Attachments: North Spread Report 11-26-08.pdf

John – please docket in 06-421 from KLJ and then forward to Commissioners, PUD and Legal

Patrick Fahn
Utility Analyst
Email: pfahn@nd.gov
Phone: (701) 328-4077

North Dakota Public Service Commission
600 E Boulevard
Bismarck ND 58505-0480
Fax: (701) 328-2410

From: Mark Anderson [mailto:mark.anderson@kljeng.com]
Sent: Monday, December 08, 2008 11:25 AM
To: Fahn, Patrick J.
Subject: PSC Project PU-06-421

Patrick:

Below is an email we received from the Wittenberg's in reference to the clean up on their property on the South Spread. Dave had been out and looked at the area awhile back and also took some pictures. Dave also passed along the concerns to TransCanada's Environmental staff and they had told us that someone would contact the Wittenberg's. It appears that has not happened to date.

Attached please find the North Spread report from 11-26-08. If you have any questions or comments, please let me know. Thank you Patrick.

Mark Anderson, PE

Kadrmass, Lee and Jackson, Inc.
1010 4th Avenue SW
P.O. Box 937
Valley City, ND 58072

Direct Dial (701) 845-9417
Cell (701) 739-6920
Fax (701) 845-0252

From: smak@nodaknet.net [mailto:smak@nodaknet.net]
Sent: Thursday, December 04, 2008 12:53 PM
To: info@kljeng.com
Subject: pipeline cleanup!!!!

625 PU-06-421 Filed: 12/8/2008 Pages: 5
Keystone Independent North Spread Report

Mark and Dave, I am writing this as of Dec. 4, 2008 we are still waiting for Michaels to finish up the cleanup on our property. (Ralph Wittenberg and Shawn, Kim and Bob's land.) I'm concerned with the amount of wood left from their mats they used on wetlands and also the rocks that were left on Ralph's land from the approached they made down the ditch. With snow on the ground now what? I have pictures id you need them. I don't even want to think of the damage that wood could do to our combines. The land is to be returned to its prior condition is this what kind of work they do? Thanks for your time.

PSC CASE NUMBER: PU-06-421

Kadmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT

1/3

Job Site: North Spread

Date: 11-26-2008

Location and
Operations Observed:

MP 1	Clean-up	
MP 7	HDD	
MP 10-16	R/W Check	public rds
MP 32	R/W Check	" "
MP 34-35	Pump station	

General Notes: Sunny but cool day on project. Temps in p.m reached 34°

MP 1

I checked mile #1 for cleanup progress. Bill Laffoon had promised Jim Belanus last week he would remove timbers, placed earlier this year to cross a natural stream. Timbers had been removed. However other timbers remain in field draws to the north of the stream. It appears they are holding back some water. I will contact Mr. Laffoon.

MP 7

HDD continues. Environmental had another breakdown.

I expect them to be back reaming on Friday.

MP 10-16

I checked the public right-of-ways for cleanup. The Road rights-of-way looked good on this 7 mile stretch that I reviewed. Ground & ditches were level, on right-of-way. I observed 2 stockpiles of dirt at 2 of the 7 sites. However they appeared to be just outside the public right of-way.

MP 32- Walsh / Pembina Co. Line.

Right-of-way clear.

MP 34-35

I observed contractor activity at the pump sta site. Underground work still continues as this site is developed & prepared for winter construction. Some plastic shelters have been built around new work areas. I also observed silt fence reinforced with straw bales along the South side of this site. They look to be effective in controlling silt management due to spring run-off.

Note: I received late word that tie in crews are being called back to continue tie-ins, due to unseasonably nice weather.

PSC CASE NUMBER: PU-06-421

Kadmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 11.26.2008

Page 3 of 3

The following deviations from the finding of facts were found:

- None -

Signature: Dennis Markusen

Print Name: Dennis Markusen