

Hamre, John G.

From: Fahn, Patrick J.
Sent: Friday, August 28, 2009 11:56 AM
To: Hamre, John G.
Subject: FW: PSC Project Number PU-06-421
Attachments: North Spread Report 8-27-09.pdf; Pic 1 North Spread 8-27-09.jpg; Pic 2 North Spread 8-27-09.jpg

John - please docket in 06-421 from KLJ and then forward to Commissioners, PUD, and Legal

Patrick Fahn
Director-Compliance and Competitive Markets
Email: pfahn@nd.gov
Phone: (701) 328-4077

North Dakota Public Service Commission
600 E Boulevard
Bismarck ND 58505-0480
Fax: (701) 328-2410

-----Original Message-----

From: Mark Anderson [<mailto:mark.anderson@kljeng.com>]
Sent: Friday, August 28, 2009 9:45 AM
To: Fahn, Patrick J.
Subject: PSC Project Number PU-06-421

Patrick:

Here is Dennis' report for the North Spread from 8-27-09 and a couple of pictures. Please let me know if you have any questions or comments. Thank you.

Mark Anderson, PE

Kadrmass, Lee and Jackson, Inc.
1010 4th Avenue SW
P.O. Box 937
Valley City, ND 58072

Direct Dial (701) 845-9417
Cell (701) 739-6920
Fax (701) 845-0252

PSC CASE NUMBER: PU-06-421

Kadrmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT

1/3

Job Site: North Spread

Date: 8-27-09

Location and

Operations Observed:

Mi. 50-53 Rock picking / gen cleanup / tillage

Mi. 54-55 No Activity

Mi. 56-58 No Activity

Mi. 102-104 No Activity

Mi. 104-110 tillage / mulch

General Notes:

Mi. 50-51. I observed 8 man crew

picking rock, tilling compacted soil, seed bed preparation,
mat removal & resoration of wetland. Henkels foreman,

Tony was on the last segment of his assignment
from Finley, North to Lenkin. Crew was doing a

nice job. Rock that was picked is being hauled off-site
to an approved location.

Mi. 52-53 No activity- mulch & seeding in-place soil tilled
& leveled. No sign of subsidence.

Mi. 54-55 - No activity Reclamation through the Forest
River valley, just East of Matecjek Dam looked very good.

Straw matting & rock was used on south bank to control

PSC CASE NUMBER: PU-06-421

Kadmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 8-27-09

Page 2 of 3

soil erosion from field run-off. Grass cover that had been seeded earlier this month was beginning to emerge.
(See pictures 2009 & 2011)

Mi. 56-58 No activity observed mulch, tillage & seeding in place.

Mi. 102-104 No activity fields have been leveled & tilled. No evidence of subsidence at this point in time.

Mi. 104-110 - No activity - crews were beginning to work on this segment.

PSC CASE NUMBER: PU-06-421

Kadmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 8-27-09

Page 3 of 3

The following deviations from the finding of facts were found:

- None -

Signature: Dennis Markusen

Print Name: Dennis Markusen



