

PSC CASE NUMBER: PU-06-421

Kadrmass
Lee &
Jackson
Engineers Surveyors
Planners

Report 39

DAILY REPORT

1/2

Job Site: North Spread

Date: 9-16-09

Location and Operations Observed: mi. 1 - Post restoration conditions.

Mi. 4-5 " " "

General Notes: I visited the Jim Belonus property in
Mi. 1 & Mi. 4 & 5 of the project. There had been
recent heavy rains. I noted the timber matting has
been removed on South end of Mi. 1. Soil has been
leveled. I did notice considerable unevenness in
ground. Area will have to be revisited.
Additional soil added and re leveled. Other wise low
spots will hold water & crop will drown out.
Mi. 4 & 5 look good. Cover Crop is growing nicely.

PSC CASE NUMBER: PU-06-421

Kadmas
Lee &
Jackson
Engineers Surveyors
Planners


DAILY REPORT (Cont.)

Date 9.16.09

Page 1 of 2

The following deviations from the finding of facts were found:

None

Signature: 

Print Name: Dennis Markusen

PSC CASE NUMBER: PU-06-421

Kadrmas
Lee &
Jackson
Engineers Surveyors
Planners

Report 40

1/2

DAILY REPORT

Job Site: North Spread

Date: 9.18.09

Location and Operations Observed: Mi. 43-48 Post restoration conditions.

General Notes: I visited miles 43-48 today.

There was no contractor activity, but I could see the results of recent restoration work.

Till able soil had been picked clean of rock, and relevelled. Cover crop in the coulees

of Mi. 46 & 47 has been seeded and has established itself well. Silt fences are in place &

functioning well. This reach should be in good condition to go into the fall & winter freeze-up.

PSC CASE NUMBER: PU-06-421

Kadrmas
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 9.18.09

Page 2 of 2

The following deviations from the finding of facts were found:

None

Signature: Dennis Markusen

Print Name: Dennis Markusen