

Hamre, John G.

From: Fahn, Patrick J.
Sent: Thursday, November 19, 2009 9:07 AM
To: Hamre, John G.
Subject: FW: PSC Project Number PU-06-421
Attachments: North Spread Report 10-1-09.pdf

John - please docket in 06-421 from KLJ and then forward to Commissioners, PU, and Legal

Patrick Fahn
Director-Compliance and Competitive Markets
Email: pfahn@nd.gov
Phone: (701) 328-4077

North Dakota Public Service Commission
600 E Boulevard
Bismarck ND 58505-0480
Fax: (701) 328-2410

-----Original Message-----

From: Mark Anderson [mailto:mark.anderson@kljeng.com]
Sent: Thursday, November 19, 2009 8:34 AM
To: Fahn, Patrick J.
Subject: PSC Project Number PU-06-421

Patrick:

Here is the report from 10-1-09. Please let me know if you have any questions or comments. The project appears to be winding down and coming to a close. We are planning to make one more review before the snow flies and it might possibly be our last report. We will let you know what we observe and find out. Thanks Patrick.

Mark Anderson, PE

Kadrmass, Lee and Jackson, Inc.
1010 4th Avenue SW
P.O. Box 937
Valley City, ND 58072

Direct Dial (701) 845-9417
Cell (701) 739-6920
Fax (701) 845-0252

PSC CASE NUMBER: PU-06-421

Kadrmass
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT # 41

Job Site: North Spread

Date: 10-1-09

Location and

Operations Observed:

Mi. 71-74

Mi. 77-81

Mi. 99-103

Mi. 104-105

Mi. 111-116

Mi. 118-121

Mi. 123-130

General Notes:

A spoke with Jeff Lafoon, ... Construction
Manager for Universal Enasco about the general status
of this project. He informed me that they hope to
be complete with all phases of this spread by the
end of this month. (October - 2009) There are several tie
ins to yet be completed, some ground reclamation at
these points, and a final walk through by environmental
division before completion. As we speak, demobilization
also continues in completed areas.

I inspected the miles shown above in
my site visits today. Although it was raining steady
I was able to access portions of these miles for checks.

PSC CASE NUMBER: PU-06-421

Kadrmias
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 10-1-09

Page 2 of 3

My general overall observation of the sites visited today was that they appeared to be in good shape, meaning rock and debris had been picked & removed, grass areas had been reseeded & mulched, & cover crop planted on much of the tillable farmland with evidence of new growth at most locations.

The Pump stations @ Mi. 77 & Mi. 123 are not complete. Tie ins to the pipe line remain @ Mi. 123.

Timber matting remains to be removed on Mi. 114. and a tie-in is in progress at Mi. 101 2 miles south of Hwy 45.

It did appear that gravel was light where the work area intersected township roads at Mi. 72/73 & Mi 102/103.

It appears that operations are progressing well. This spread generally looks much better overall than it did a year ago. I will continue to monitor until complete.

PSC CASE NUMBER: PU-06-421

Kadrmass
Lee &
Jackson
Engineers Surveyors
Planners

DAILY REPORT (Cont.)

Date 10-1-09

Page 3 of 3

The following deviations from the finding of facts were found:

No deviations noted.

Signature: Dennis Markusen

Print Name: Dennis Markusen