




Mr. Darrell Nitschke
Executive Director
North Dakota Public Service Commission
12th Floor, State Capitol
600 E. Boulevard Avenue
Bismarck, ND 58505-0480



Dear Mr. Nitschke:

In re: Enbridge Energy, Limited Partnership
Case No. PU-07-108
Alberta Clipper Pipeline, Pembina County, North Dakota

Enclosed for filing in the above referenced case please find two copies of Enbridge Energy, Limited Partnership's response to Mr. Patrick Fahn's letter dated August 19, 2015, and subsequent correspondence of February 2, 2016 and April 4, 2016, regarding a Construction Inspection Report for this Project.

If you have any questions regarding this response, please contact Sally Joyce at 713-353-6328 or Mary Cohen at 218-464-5703.

Sincerely,


Sally Joyce

Enc.

110 PU-07-108 Filed: 6/28/2016 Pages: 5
Response to request for report re reclamation activities

Enbridge Energy, Limited Partnership
Sally Joyce



June 28, 2016

Enbridge Energy, Limited Partnership provides the enclosed information in response Mr. Patrick Fahn's request dated August 19, 2015 regarding Final Construction Inspection Reports, and subsequent correspondence of February 2, 2016 and April 4, 2016:

Case No. PU-07-108

On December 31, 2007, the North Dakota Public Service Commission issued an order in this case authorizing the Company to construct 28 miles of 36-inch liquid petroleum pipeline adjacent and parallel to its existing pipelines in Pembina County, North Dakota (the Alberta Clipper Pipeline).

As per the post-construction inspection report, the following information should be provided:

Monitoring of open cut roads which had settled and formed slight depressions. (See Appendix A, Photos 11, 27, 30, 34, and 36 in the post construction report)

Please find the following attached:

Attachment A includes new photos taken on June 9, 2016 at the road crossings discussed in the post-construction inspection report. All crossing have been restored. There are no negative effects to local traffic as it relates to the original construction.

Enbridge Energy, Limited Partnership
Follow up to Post Construction Inspection Report
Case No. PU-07-108
Attachment A

Photo 1 - Southeast of Mile 799 at crossing of 91st Street NE

(This location is Photo 11 from the Post Construction Inspection Report)



Photo 2 - 148th Ave NE just to the southeast of Mile 778

(This location is Photo 27 from the Post Construction Inspection Report)



Enbridge Energy, Limited Partnership
Follow up to Post Construction Inspection Report
Case No. PU-07-108
Attachment A

Photo 3 - 104th Street NE to the southeast of Mile 781

(This location is Photo 30 from the Post Construction Inspection Report)



Photo 4 - 154th Ave NE at Mile 787

(This location is Photo 34 from the Post Construction Inspection Report)



Enbridge Energy, Limited Partnership
Follow up to Post Construction Inspection Report
Case No. PU-07-108
Attachment A

Photo 5 - 98th St SE at approximately Mile 789.5

(This location is Photo 36 from the Post Construction Inspection Report)

