


Belle Fourche Pipeline Company  
PO Drawer 2360  
Casper WY 82602

November 16, 2015

Patrick Fahn  
Director Compliance and Competitive Markets  
Public Service Commission – North Dakota  
600 East Boulevard  
Dept. 408  
Bismarck ND 58505



RE: Post Construction Inspections PU-07-596

As noted in our October 23<sup>rd</sup> letter, Belle Fourche offers the additional information below and attached, regarding the reclamation progress at the location of specific interest in the above captioned case. In your August 28<sup>th</sup> 2015 letter, based on the third party inspector's post construction notes, you cited some concern in the reclamation and clean up around the location in the NE/4 SW/4 Section 6 T151N, R101W.

Belle Fourche has continued to address any reclamation issues and continues to work in this area to ensure that reclamation is completed satisfactorily. To that end some additional erosion control measures were taken this past summer on the location. I am including some updated pictures taken last week showing the current conditions at the location of concern.

Feel free to contact me directly at 307-266-0275, if you need any further information or if you have any questions.

Sincerely,

Ken Dockweiler  
Director Land Government and Compliance

Attachments: 2

CC: Bob Dundas  
Hank True  
Tad True  
Manuel Lojo

94 PU-07-596 Filed: 11/23/2015 Pages: 3  
Additional information in response to Aug. 28, 2015  
letter re post construction inspection

Belle Fourche Pipeline Company  
Ken Dockweiler



