



Safety Issue Resolution Process Track Issue

Safety Menu:

- Enter Safety Data
- Issues Logged By Me
- Track Issue Status
- Assigned Issues
- Elevation Admin Report
- Elevated Issues Report
- View Reports
- Supervisor Reports
- SIRP Post Reports
- GM Admin Reports
- Administration
- Log Off
- SIRP Manual
- HOME

Safety Log Details for Issue TWI000009768

Reporting Details

Reporting Date 10/06/2009
Reporting Employee Details:
 Employee Id 4611133
 Last Name HUFF First Name RONALD
 Phone 701-667-2270 E-Mail RONALD.HUFF@BNSF.COM
 Address 1727 N GRANDVIEW LN #321, BISMARCK,ND, 58503

Safety log Details

Craft ENGINEER Reporting method Verbal
 Station Name BISMARCK Sub Division JAMESTOWN
 Division TWI Location OTHER
 Estimated Issue Close Date 01/14/2010 Actual Issue Close Date 01/15/2010
 Issue Category VEGETATION
 Description

Item:

AT MP 196.3 THERE IS A TREE OBSTRUCTING THE VIEW FOR EAST BOUND TRAFFIC, TREE NEEDS TO BE CUT BACK.

Interim Protection:

JAMES CHASE - 10/06/2009 RESPONSABLE PERSON TO ENTER.

Corrective Action / Protection:

PATRICK YAUNEY- 01/15/2010 TREE HAS BEEN CUT DOWN THIS DATE
 PATRICK YAUNEY- 01/04/2010 TREE HAS NO LEAVES AND IS NOT A VISION PROBLEM AT THIS TIME
 PAY
 PATRICK YAUNEY- 11/30/2009 NO LONGER A VISIBILITY ISSUE UNTIL SPRING
 PATRICK YAUNEY- 11/30/2009 LEAVES HAVE FALLEN OFF TREE WILL REVISIT IN THE SPRING
 PATRICK YAUNEY- 10/16/2009 DITCHER PULLED TREES DOWN PAY

Division **Safety Manager Comments:** No comments available.

Notes:

Responsible Person Details

Last Name YAUNEY First Name PATRICK
 Department MAINTENANCE OF WAY Issue Status Closed
 Job Title ROADMASTER

31 RR-10-26 Filed: 3/4/2010 Pages: 1
 Exhibit 7 – Safety Issue Resolution Process

BNSF Railway Company

