



North Dakota Gathering System

## Weekly Construction Progress Report

Case #: PU-10-218

Project: BakkenLink Pipeline

Week Ending: January 11<sup>th</sup>, 2014

Title	Name	Company	Office Phone	Cell Phone
Project Director	Darren Snow	BakkenLink	701-751-3401	701-204-1619
Mainline Contractor	Torsten Leines	Alpha Oil & Gas	701-842-2855	612-916-8417
Environmental Inspector	Troy Portnoff	Aspen Environmental		

### Brief Description of Week's Activities

Working with landowners and the NRCS on tree & shrub mitigation plan. Worked to install aerial marker numbers.

### Brief Description of Next Week's Activities

Continue to work with landowners on the tree & shrub mitigation plan.

### Mainline Construction

Description	Week Complete	% Week Complete	Total Complete	% Total Complete
Rough Clean-up				100%
Final Clean-up				100%
Re-Seeding				100%

### Project Site Safety

Conduct daily JSA's.

Signatory	Date
Darren Snow	1/12/14



North Dakota Gathering System

## Weekly Construction Progress Report

Case #:PU-10-218

Project: BakkenLink Pipeline

Week Ending: January 4<sup>th</sup>, 2014

Title	Name	Company	Office Phone	Cell Phone
Project Director	Darren Snow	BakkenLink	701-751-3401	701-204-1619
Mainline Contractor	Torsten Leines	Alpha Oil & Gas	701-842-2855	612-916-8417
Environmental Inspector	Troy Portnoff	Aspen Environmental		
<b>Brief Description of Week's Activities</b>				
Working with landowners and the NRCS on tree & shrub mitigation plan.				
<b>Brief Description of Next Week's Activities</b>				
Continue to work with landowners on the tree & shrub mitigation plan.				
<b>Mainline Construction</b>				
Description	Week Complete	% Week Complete	Total Complete	% Total Complete
Rough Clean-up	0 ft	0%	494,303 ft	100%
Final Clean-up		0%		100%
Re-Seeding		0%		100%
<b>Belfield Lateral Construction</b>				
Description	Week Complete	% Week Complete	Total Complete	% Total Complete
Rough Clean-up	0 ft	0%	19,296 lf	100%
Final Clean-up			19,296 ft	100%
Re-Seeding		0%		100%
<b>Project Site Safety</b>				
No construction activity on the ROW.				
<b>Signatory</b>			<b>Date</b>	
Darren Snow			1/5/14	



North Dakota Gathering System

## Weekly Construction Progress Report

Case #: PU-10-218

Project: BakkenLink Pipeline

Week Ending: December 29th, 2013

Title	Name	Company	Office Phone	Cell Phone
Project Director	Darren Snow	BakkenLink	701-751-3401	701-204-1619
Mainline Contractor	Torsten Leines	Alpha Oil & Gas	701-842-2855	612-916-8417
Environmental Inspector	Troy Portnoff	Aspen Environmental		
<b>Brief Description of Week's Activities</b>				
Working with landowners and the NRCS on tree & shrub mitigation plan.				
<b>Brief Description of Next Week's Activities</b>				
Continue to work with landowners on the tree & shrub mitigation plan.				
<b>Mainline Construction</b>				
Description	Week Complete	% Week Complete	Total Complete	% Total Complete
Rough Clean-up	0 ft	0%	494,303 ft	100%
Final Clean-up		0%		100%
Re-Seeding		0%		100%
<b>Belfield Lateral Construction</b>				
Description	Week Complete	% Week Complete	Total Complete	% Total Complete
Rough Clean-up	0 ft	0%	19,296 lf	100%
Final Clean-up			19,296 ft	100%
Re-Seeding		0%		100%
<b>Project Site Safety</b>				
No construction activity on the ROW.				
<b>Signatory</b>			<b>Date</b>	
Darren Snow			12/29/13	



North Dakota Gathering System

## Weekly Construction Progress Report

Case #: PU-10-218

Project: BakkenLink Pipeline

Week Ending: December 22nd, 2013

Title	Name	Company	Office Phone	Cell Phone
Project Director	Darren Snow	BakkenLink	701-751-3401	701-204-1619
Mainline Contractor	Torsten Leines	Alpha Oil & Gas	701-842-2855	612-916-8417
Environmental Inspector	Troy Portnoff	Aspen Environmental		
<b>Brief Description of Week's Activities</b>				
Working with landowners and the NRCS on tree & shrub mitigation plan.				
<b>Brief Description of Next Week's Activities</b>				
Continue to work with landowners on the tree & shrub mitigation plan.				
<b>Mainline Construction</b>				
Description	Week Complete	% Week Complete	Total Complete	% Total Complete
Rough Clean-up	0 ft	0%	494,303 ft	100%
Final Clean-up		0%		100%
Re-Seeding		0%		100%
<b>Belfield Lateral Construction</b>				
Description	Week Complete	% Week Complete	Total Complete	% Total Complete
Rough Clean-up	0 ft	0%	19,296 lf	100%
Final Clean-up			19,296 ft	100%
Re-Seeding		0%		100%
<b>Project Site Safety</b>				
No construction activity on the ROW.				
<b>Signatory</b>			<b>Date</b>	
Darren Snow			12/23/13	