

Coteau Properties Company
Notice of Violation No. 1004
Case No. RC-10-598
PSC Staff Exhibit List

1. PSC Staff Exhibit #1 – Aerial View of Portions of Freedom Mine, including Permits 8102 and 8203;
2. PSC Staff Exhibit #2 – Topographical Map of Portions of Freedom Mine, including Permits 8102 and 8203;
3. PSC Staff Exhibit #2A – Topographical Map of Portions of Freedom Mine, including Permits 8102 and 8203, with arrows;
4. PSC Staff Exhibit #3 – September 29, 2010 Photograph, South Side of Haulroad;
5. PSC Staff Exhibit #4 – September 29, 2010 Photograph, North Side of Haulroad;
6. PSC Staff Exhibit #5 – September 30, 2010 Photograph, North Side of Haulroad;
7. PSC Staff Exhibit #6 – September 30, 2010 Photograph, North Side of Haulroad;
8. PSC Staff Exhibit #7 – September 30, 2010 Photograph, North Side of Haulroad;
9. PSC Staff Exhibit #8 – September 30, 2010 Photograph, North Side of Haulroad;
10. PSC Staff Exhibit #9 – September 30, 2010 Photograph, North Side of Haulroad;
11. PSC Staff Exhibit #10 – October 20, 2010 Photograph, North Side of Haulroad;
12. PSC Staff Exhibit #11 – October 20, 2010 Photograph, North Side of Haulroad;
13. PSC Staff Exhibit #12 – September 17, 2009 William Kirk Haulroad Certification Report (3 pages);
14. PSC Staff Exhibit #13 – September 2, 2010 Mike Berg Inspection Report (7 pages);

15. PSC Staff Exhibit #14 – September 29, 2010 Mike Berg Inspection Report (5 pages);
16. PSC Staff Exhibit #15 – September 30, 2010 Mike Berg Inspection Report (4 pages);
17. PSC Staff Exhibit #16 – NDAC 69-05.2-24-01(2)(a);
18. PSC Staff Exhibit #17 – NDAC 69-05.2-16-08(1)(c);
19. PSC Staff Exhibit #18 - Notice of Violation 1004 Served October 4, 2010 (3 pages);
20. PSC Staff Exhibit #19 – Modification of Notice of Violation 1004;
21. PSC Staff Exhibit # 20 – NACT 8102 – Surface Coal Mining and Reclamation Operation Permit Conditions (3 pages);
22. PSC Staff Exhibit # 21 – NACT 8203 – Surface Coal Mining and Reclamation Operation Permit Conditions (3 pages).