

Bison 2 Weekly Construction Report
PU-11-57
Week Ending: 04/01/12

Michels crews inspecting and repairing erosion controls. Transformers, switches and other materials are being delivered to turbine sites.

Hooper Construction has 3 employees working at Bison Substation. Two power transformers and four circuit breakers have been delivered to the substation.