



Glen Ullin Energy Center Project

Progress Report

Case #: PU-11-662

Week Ending 11/01/2019

Safety: An employee injured his finger when he was loading rebar into a dumpster. His finger was pinch between the rebar and the dumpster resulting in a laceration requiring stitches. The employee has returned to work.

Environmental: An environmental spill occurred when a forklift tipped on its side on 10/26/2019 at 1550. Less than one gallon of hydraulic oil and antifreeze spilled from the forklift. The spill was contained and the soil was collected and placed in a sealed container. The contaminated material will be disposed of at an approved facility. An Environmental Incident Report was completed and submitted to the North Dakota Department of Environmental Quality.

The Substation was energized this week.

Collection Circuit one was energized and test power was generated on five turbines.

Turbines erection continues.

Workforce:

ALLETE Clean Energy	- 5
Wanzek	- 70
Wanzek Sub Contractors	- 10
General Electric	- 16
TOTAL	- 101