

Date <i>9-3-14</i>	Day <i>Wednesday</i>
Hours Worked	
Working Days Charged	Total Working Days to Date
Reasons for Time not Charged	

**Weather**

*Sunny 70's*

**Engineering Staff**

*Josh Kadrmaz, HEI*

**Work in Progress**

*1530 Arrived at north end of pipeline route. Begin traveling south along route to location of current construction.*

*1545 Meet Paige Travis. Informed that I need safety orientation training from Tim Banks before being allowed on site. Mr. Travis will escort me in limited areas until Tim gets back on site.*

*1610 Review live stock pond, which will require directional boring to avoid wetland impacts.*

*1620 Move to review 2nd potential wetland, south*

**Contractor's Labor Force**

*NA*

**Contractor's Equipment Summary**

*NA*

**Project Visitors**

*NA*

*paigetravis@yahoo.com*



**Paige Travis**  
 Construction Manager  
 Mainline Projects US  
 Tel 989-330-7834  
 paige.travis@enbridge.com

**Enbridge Energy Company**  
 Enbridge (U.S.), Inc.  
 Duluth Technology Village  
 44 E Superior St Suite 165  
 Duluth, MN 55802  
 U.S.A.



**BOB JEFFRIES**  
 Field Superintendent

P.O. Box 80745  
 Billings, MT 59108

(406) 850-9277 (cell)  
 jeffriesokiejj@yahoo.com

**Phone (406) 652-8327 • Fax (406) 652-8320**

## Communications/Instructions/Remarks

- of 11th St SW and east of the pipe line.
- 1635 Bob Jeffries, TRE Constructors, stated the adjacent residents leveled the trees in this wetland. The pipe line is already laid out to avoid this group of trees, so it does not appear likely that the trees would have been removed as part of the pipe line construction. Also the resident's mobile home is reported to have been put in place after ROW was purchased and the siting permit was issued.
- 1640 Tim Banks arrives onsite to issue safety orientation to H&E1 personnel.
- 1650 Bob provides a vehicle tour of the pipe line route from the residence to the south side of the Livestock pond.
- 1720 Move with Paige to south end of the pipe line alignment to review the 3rd wetland for potential impacts.
- 1735 Shawn (Paige's supervisor) meets us at the south end of the project.
- 1755 Leave site for Fargo office. Erosion control consisted of earthen berms or top soil cuts to direct run off to localized discharge points which appeared to be effectively stabilized with bio roll. Dewatering bags were also on site and had been used to retain sediment during dewatering activities. Shawn stated he would contact me to schedule the final inspection at project completion. 16 photos taken during site visit.

  
Project Manager Signature