

Bison 4 Weekly Construction Report

Case No. PU-13-127

Week Ending 03/30/14

Wanzek began removing rock and some top soil stripping in area 3.

Michels mobilized to site for substation construction, they also received substation steel structures.

Work Force

Minnesota Power – 1

Wanzek – 8

Michels - 4

Bison 4 Weekly Construction Report

Case No. PU-13-127

Week Ending 03/23/14

Bison 4 Substation main power transformer filled and tested

Wanzek inspecting / repairing silt fence and prepping equipment.

Work Force

Minnesota Power – 1

Wanzek – 6

Michels