


EXHIBIT
tabbles
B23

- Legende**
- G GS-14-230 Filed 06/30/2015 Pages: 1
 - G 67 Exhibit B23 Public Service Commission
 - G 67 GS-14-229 Filed 06/30/2015 Pages: 1
 - G 66 Exhibit B23
 - G 66 GS-13-886 Filed 06/30/2015 Pages: 1
 - G 67 Exhibit B23
 - G 67 GS-13-885 Filed 06/30/2015 Pages: 1
 - G 66 Exhibit B23
 - G 66 GS-13-884 Filed 06/30/2015 Pages: 1
 - G 66 Exhibit B23
- Gas Office Note
 - <all other values>
 - Created
 - Field Verified
 - Completed
 - Gas Field Line
 - Excess Flow Valve
 - CP Rectifier
 - CP Test Station
 - CP Isolated Inspection
 - CP Ground Bed
 - CP Galvanic Anode
 - Gas Marker Ball
 - Gas Service Point
 - Multiple Meter Service
 - Single Meter Service
 - No Meter Service
 - Gas Station
 - <all other values>
 - District Regulator Station
 - Large Customer Station
 - Rural Regulator Station
 - Town Border Station

1: 2,996



Notes
Case GS-14-229
Damage occurred inside Located area.